

LICENSEE EVENT REPORT

LER 83-34/3L

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 VTVYS1 200-00000-00 341111 4 5  
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T

01 REPORT SOURCE L605000271 7120683 8010584 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

02 During normal operation while performing surveillance testing, condensate storage  
03 tank level instrument LT-107-5B was found out of adjustment which resulted in the set  
04 point for the HPCI suction transfer being lower than that allowed in T. S. Table 3.2.1.  
05 There were no significant occurrences as a result of this event. There were no  
06 adverse affects to public health and safety. There have been no similar occurrences  
07 reported to the commission.

08 7 8 9 80

09 IB 11 E 12 E 13 INSTRU 14 T 15 Z 16  
7 8 9 10 11 12 13 14 15 16 17 18 19 20  
17 LER NO. REPORT NUMBER 83 — 034 — 03 L — 0  
21 22 23 24 25 26 27 28 29 30 31 32  
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
E 18 Z 19 Z 20 Z 21 0000 N 23 Y 24 A 25 G080 26  
33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27


10 The cause of this event was a shift of the zero of the level transmitter. The trans-  
11 mitter was realigned and the setpoint was verified correct after the adjustment.  
12 LT-107-5B is a model 555-111BDAA3PB1 GE/MAC Transmitter.  
13  
14

15 E 28 100 29 NA B 31 Surveillance Testing 32  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
16 Z 33 Z 34 NA NA NA 36  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
17 000 37 Z 38 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
PERSONNEL INJURIES NUMBER DESCRIPTION  
18 000 40 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50  
LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
19 Z 42 NA  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

20 N 44 8401160127 340105 PDR ADOCK 05000271 S PDR NRC USE ONLY  
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

NAME OF PREPARER J. P. Pelletier

PHONE (802) 257-7711



# VERMONT YANKEE NUCLEAR POWER CORPORATION

P. O. BOX 157  
GOVERNOR HUNT ROAD  
VERNON, VERMONT 05354

VYV 84-C06

January 5, 1984

United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

ATTENTION: Dr. Thomas E. Murley, Regional Administrator

REFERENCES: Operating License DPR-28  
Docket No. 50-271  
Reportable Occurrence No. LER 83-34/3L

Dear Sir:

As defined by Technical Specifications for the Vermont Yankee Nuclear Power Station, Section 6.7.B.2, we are reporting the attached Reportable Occurrence as LER 83-34/3L.

Very truly yours,

James P. Pelletier  
Plant Manager

RDP/drc

IE22  
1/1