

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	N	P	I	N	1	2	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	4	5				
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33				
LICENSEE CODE														LICENSE NUMBER										LICENSE TYPE					CAT 58	

0	1	L	6	0	5	0	0	0	2	8	2	7	1	1	2	1	8	3	8	1	2	2	1	8	3	9
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33
CON'T		REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE							

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During review of the surveillance program, it was discovered that SP1096-1, Monthly
0 3 | Station Battery Test, was not completed as scheduled. Subsequent testing showed the
0 4 | battery was operable during the period. Tech Spec 4.0 applies. Recent similar event
0 5 | was RO 83-28.
0 6 |
0 7 |
0 8 |

0	9	Z	Z	11	A	12	C	13	Z	Z	Z	Z	Z	14	Z	15	Z	16	17	8	3	—	0	3	2	0	3	L	—	0	18	G	19	Z	20	Z	21	0	0	0	0	N	23	N	24	Z	25	Z	9	9	9	26
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50									
SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE					COMP. SUBCODE		VALVE SUBCODE		EVENT YEAR		SEQUENTIAL REPORT NO		OCCURRENCE CODE		REPORT TYPE		REVISION NO		ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Temporary change in responsibilities led to the personnel error. The event was
1 1 | discussed with involved personnel. A scheduling change was made which should help
1 2 | prevent recurrence.
1 3 |
1 4 |

1	5	E	28	1	0	0	29	NA	B	31	Review of surveillance program	32	33	Z	34	NA	NA	35	36	37	0	0	0	38	Z	39	NA	40	0	0	0	41	NA	42	Z	43	NA	44	N	45	NA		
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50
FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION										ACTIVITY CONTENT		AMOUNT OF ACTIVITY		LOCATION OF RELEASE		PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY		PUBLICATION													

NAME OF PREPARER A. A. HunstadPHONE 612-388-1121



DMB

Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

December 21, 1983

Regional Administrator
Region III
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Missed Surveillance Test

The License Event Report for this occurrence is attached.

This event is reported in compliance with Technical Specification 6.7.B.2.(c), since it indicates an observed inadequacy in the implementation of administrative or procedural controls which threaten to cause reduction of degree of redundancy provided in reactor protection systems or engineered safety feature systems.

David Musolf

David Musolf
Manager - Nuclear Support Services

DMM/TAP/bd

cc: NRC Document Control Desk (1)
NRC Resident Inspector
MPCA
Attn: J W Ferman

Attachment

FE2211
DEC 27 1983