

LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	C	0	F	S	V	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	2	0	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT 58	

CON'T

0 1 7 8

REPORT SOURCE

60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

On November 16, 1983, with the reactor operating near 70% power, it was determined that Specification SR 5.4.4, PCRV Cooling Water System Temperature Scanner Surveillance Requirement, had not been performed within the required surveillance interval. This event is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)3. No effect on public health or safety. No accompanying occurrence.

Similar Reports: 80-78, 82-039.

0	8											80	
7	8	9	SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE				COMP. SUBCODE	VALVE SUBCODE	
0	9		Z	Z	A	X	Z	Z	Z	Z	Z	Z	Z
7	8		9	10	11	12	13	14	15	16	17	18	19
(17) LER/RD REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.			
8		3		0		5		0		1			
21		22		23		24		25		26			
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED			
H		Z		Z		Z		0		Y			
18		19		20		21		22		23			
23		24		25		26		27		28			
NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER									
N		Z		Z									
24		25		26									
42		43		44									

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 A temporary scheduling technician did not ensure that the Technical Specification
1 1 Surveillance Test, SR 5.4.4-M/5.4.4-A1, was delivered to the responsible department
1 2 prior to the "late" date. Personnel were reminded of their duties and the importance
1 3 of adhering to the Technical Specification Surveillance Testing Program requirements.
1 4 The test was successfully completed on November 21, 1983. No future corrective
7 8 9 actions are anticipated or required. METHOD OF

actions are anticipated or required.

FACILITY STATUS		% POWER	OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
1	5	E	(28)	0 7 0	(29)	N/A	A	(31)	Surveillance Program Review

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 7 33 7 34 N/A

LOCATION OF RELEASE (36)

N/A

PERSONNEL EXPOSURES			
NUMBER	TYPE	DESCRIPTION	(39)
1 7	0 0 0 (37)	Z (38)	N/A

PERSONNEL INJURIES

NUMBER	DESCRIPTION
41	

1 8 0 0 0 (40) N/A

1		9		Z		(42)		N/A		8401100337 831228	

7 8 9 10
PUBLICATION
ISSUED - DESCRIPTION (45)
PDR ADOCK 05000267
S PDR
NRC USE ONLY

7 8 9 10 68 69 80

NAME OF PREPAREF.

PHONE: (303) 785-2224




Public Service Company of Colorado

16805 Road 19 1/2, Platteville, Colorado 80651-9298

50-267

December 29, 1983
Fort St. Vrain
Unit No. 1
P-83413



Mr. John T. Collins, Regional Administrator
Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive
Suite 1000
Arlington, Texas 76011

Reference: Facility Operating License
No. DPR-34

Docket No. 50-267

Dear Mr. Collins:

Enclosed please find a copy of Reportable Occurrence Report No. 50-267/83-050, Revised Final, submitted per the requirements of Technical Specification AC 7.5.2(b)3.

Also, please find enclosed one copy of the Licensee Event Report for Reportable Occurrence Report No. 50-267/83-050.

Very truly yours,

Don Warembourg

Don Warembourg
Manager, Nuclear Production

DW/djm

Enclosure

cc: Director, MIPC

H005
1/1

REPORT DATE: December 29, 1983
 Determined
OCCURRENCE DATE: November 16, 1983

REPORTABLE OCCURRENCE 83-050
Issue 1
Page 1 of 3

FORT ST. VRAIN NUCLEAR GENERATING STATION
PUBLIC SERVICE COMPANY OF COLORADO
16805 WELD COUNTY ROAD 19 1/2
PLATTEVILLE, COLORADO 80651-9298

REPORT NO. 50-267/83-050/03-X-1

Revised Final

IDENTIFICATION OF
OCCURRENCE:

On November 16, 1983, with the reactor operating near 70% power, it was determined that Specification SR 5.4.4, PCRV Cooling Water System Temperature Scanner Surveillance Requirement, had not been performed within the required surveillance interval. This event is reportable per Fort St. Vrain Technical Specification AC 7.5.2(b)3.

EVENT
DESCRIPTION:

On November 16, 1983, during a review of the surveillance scheduling program, it was determined that a surveillance test with a "late" date of November 13, 1983, had not yet been completed. The surveillance test (SR 5.4.4-M/5.4.4-A1) is a combination monthly and annual test. The monthly section had been last performed on October 6, 1983. The "late" date (which includes the allowed +25%) was listed as November 13, 1983, but due to a delivery problem, the surveillance was received by the responsible department after the "late" date. The responsible department successfully completed the surveillance by November 21, 1983.

CAUSE
DESCRIPTION:

Personnel Error.

The regular scheduling technician was absent due to health reasons, and a temporary scheduling technician was performing the normal duties. A part of these duties is to update and review the surveillance test listing to ensure that all Technical Specification surveillance tests are issued and completed within the specified test interval. The temporary scheduling technician did not assure that all Technical Specification Surveillance Requirements were met with regard to recordkeeping as required in Section 4.1.5 (c) of the Station Manager Administrative Procedure-1 (SMAP-1).


CORRECTIVE
ACTION:

Surveillance test SR 5.4.4-M/5.4.4-A1 was completed successfully on
November 21, 1983.

Both the temporary and regular scheduling technicians were reminded
of their duties and the importance of meeting the Technical
Specification surveillance interval requirements.

No further corrective actions are anticipated or required.

Prepared By:


Owen J. Clayton
Senior Technical Services Technician


Reviewed By:


Frank L. Novachek
Technical Services Engineering Supervisor

Reviewed By:


L. M. McBride
Station Manager

Approved By:


Don Warembourg
Manager, Nuclear Production