

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	I	D	I	C	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5					
7	8	LICENSEE CODE							14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	31	32	33	34	35

CON'T

REPORT
SOURCE

REPORT SOURCE: L 6 0 1 5 0 1 0 1 0 1 3 1 1 5 7 1 1 2 1 1 9 8 1 3 5 0 1 1 0 1 3 1 8 1 4 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

ON 12-19-83, WHILE INVESTIGATING AN 11-25-83 EVENT WHERE THE SAMPLE PUMP FOR THE UNIT VENT EFFLUENT MONITOR (VRS-1500) HAD BEEN FOUND INOPERABLE, IT WAS DISCOVERED THAT THE ACTION REQUIREMENT OF TECHNICAL SPECIFICATION 3.3.3.10 TABLE 3.3-13 ITEMS 3.b AND 3.c HAD NOT BEEN FULFILLED. THE CONTINUOUS CHARCOAL AND PARTICULATE SAMPLES HAD NOT BEEN OBTAINED. DURING THE TIME VRS-1500 WAS INOPERABLE (0248 HOURS ON 11-25-83 TO 1538 HOURS ON 11-26-83) NO RADIOACTIVE RELEASES OCCURRED FROM THE UNIT-1 VENT. THE PUBLIC HEALTH AND SAFETY WERE NOT AFFECTED.

SYSTEM CODE M C 11		CAUSE CODE D 12		CAUSE SUBCODE Z 13		COMPONENT CODE Z Z Z Z Z Z 14		COMP SUBCODE Z 15		VALVE SUBCODE Z 16	
LER/RO REPORT NUMBER 17		EVENT YEAR 8 3 22		SEQUENTIAL REPORT NO. 1 2 1 24		OCCURRENCE CODE 0 1 28		REPORT TYPE T 30		REVISION NO. 0 32	
ACTION TAKEN G 13 33		FUTURE ACTION Z 19 34		EFFECT ON PLANT Z 20 35		SHUTDOWN METHOD Z 21 36		HOURS 0 0 0 0 0 0 37		ATTACHMENT SUBMITTED N 23 41	
CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27		PRIME COMP. SUPPLIER Z 25 43		NPRD-4 FORM SUB N 24 42		COMPONENT MANUFACTURER Z 9 9 9 44					

THIS EVENT WAS THE RESULT OF INADEQUATE PROCEDURES. THE CONTINUOUS SAMPLING REQUIREMENTS, REFERENCED BY ACTION ITEM NO. 32, WERE NOT RECOGNIZED AND INCORPORATED IN APPROVED PROCEDURES. TO PREVENT RECURRENCE, AN AUXILIARY SAMPLE APPARATUS IS NOW AVAILABLE ALLOWING CONTINUOUS PARTICULATE AND CHARCOAL SAMPLING SHOULD THE NORMAL SAMPLE PUMP FAIL FOR VRS-1500. PROCEDURES WERE MODIFIED TO UTILIZE AUXILIARY SAMPLING EQUIPMENT.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	0	17	18	23	B	31
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		TECHNICIAN OBSERVATION		LOCATION OF RELEASE	
1	6	Z	33	Z	34	NA		NA	
PERSONNEL EXPOSURES		PERSONNEL INJURIES		LOSS OF OR DAMAGE TO FACILITY		PUBLICITY		ISSUED	
1	7	0	10	0	10	0	10	Z	42
NUMBER		NUMBER		TYPE		DESCRIPTION		DESCRIPTION	
0	10	0	10	0	10	0	10	N	44
TYPE		DESCRIPTION		DESCRIPTION		DESCRIPTION		DESCRIPTION	
NA		NA		NA		NA		NA	

8401100340 840103
PDR ADOCK 05000315
S PDR

NRC USE ONLY

NAME OF PREPARED J. L. RISCHLING

(616) 465-5901



INDIANA & MICHIGAN ELECTRIC COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106
(616) 465-5901

January 3, 1984

Mr. J.G. Keppler, Regional Administrator
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137


Operating License DPR-58
Docket No. 50-315

Dear Mr. Keppler:

Pursuant to the requirements of the Appendix A Technical Specifications,
the following report/s are submitted:

RO 83-121/01T-0

Sincerely,


W.G. Smith, Jr.
Plant Manager

/clm

cc: J.E. Dolan
M.P. Alexich
R.F. Kroeger
H. Brugger
E. Swanson/N. DuBry RO:III
R.C. Callen MPSC
G. Charnoff, Esq.
J.M. Hennigan
R.O. Bruggee
INPO
PNSRC
J.F. Stietzel
E.L. Townley
Dir., IE (30 copies)
Dir., MIPC (3 copies)

JAN 5 1984

FE22
11