

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

0 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 With the unit in cold shutdown while performing HNP-2-3456, RPS M-G set overvoltage,  
0 3 underfrequency, and under voltage FT&C, the underfrequency trip setpoint was found  
0 4 at 54.1 HZ for RPS M-G Set "A". The expected setpoint per HNP-2-3456 is  $58 \pm 0.5$  HZ.  
0 5 The Technical Specification limit is  $\geq 57$  HZ (4.8.2.1.2.b.3). No significant events  
0 6 occurred as a consequence. There are no similar occurrences.  
0 7  
0 8  
0 9

0 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 The underfrequency trip setpoint was found too low because the pre-op test on the  
1 1 system had caused it to be set to 54 HZ. The surveillance test, HNP-2-3456, contains  
1 2 a setpoint more conservative than Technical Specifications. No procedure revision  
1 3 is necessary. The setpoint was adjusted per HNP-2-3456.  
1 4

1 5 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80

NAME OF PREPARER R. T. Nix  
Superintendent of Maintenance

PHONE: (912) 367-7781

7901300150

NRC USE ONLY