

CONTROL BLOCK: 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

1 G A E I H 2 2 0 0 0 0 0 0 0 0 0 0 0 3 4 1 1 1 1 1 4 5

DN'T

1 L 6 0 5 0 0 0 3 6 6 7 0 1 0 2 7 0 8 0 1 1 7 7 9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10

2 | While in cold shutdown and attempting to perform HNP-2-3173, reactor pressure
3 | instrument FT&C, relay 2B21-K34A failed to operate with the actuation of 2B21-N021A.
4 | There were no significant consequences to this event. This is not a repetitive
5 | occurrence.
6 |
7 |
8 |

9 I B 11 E 12 A 13 R E L I A Y X 14 A 15 Z 16
17 7 1 9 0 0 6 0 3 L 0
A 18 Z 13 Z 20 Z 21 0 0 0 0 N 23 N 24 N 25 A 1 0 9 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27

28 | The reason that Relay 2B21-K34A failed to operate was that the coil was open. The
29 | relay, an Agastat model GPD, was repaired by replacing the coil. Procedure HNP-2-3173
30 | was then performed satisfactorily.
31 |
32 |
33 |
34 |

35 G 28 0 0 0 0 29 NA 30 B 31 Surveillance Test 32
33 Z 32 Z 34 NA 35 NA 36
37 0 0 0 37 Z 38 NA 39
40 0 0 0 40 NA 41
42 Z 42 NA 43
44 N 44 NA 45

NAME OF PREPARER

R. T. Nix

Superintendent of Maintenance

PHONE:

(912) 367-7781

NRC USE ONLY

7901300171