

LICENSEE EVENT REPORT

UPDATE REPORT:

PREVIOUS REPORT DATE: 1-25-82

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 N C B E P 2 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 57 CAT 58

CON'T

0 1 REPORT SOURCE L 6 0 5 0 - 0 3 2 4 7 1 2 2 8 8 1 8 0 4 0 9 8 4 9
7 8 60 61 DOCKET NUMBER 63 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During unit power operation, while performing No. 4 diesel generator monthly load test,
0 3 PT-12.2d, it was found that the diesel generator, Model No. F5-1316-HS6, manufactured
0 4 by Nordberg, would not assure a steady load > 1000KW. At the time of this event, the
0 5 remaining diesel generators were operable. This event did not affect the health and
0 6 safety of the public.

0 7
0 8 Technical Specifications 3.8.1.1, 6.9.1.9b
7 8 9 80

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
7 8 9 10 11 12 13 14 15 16
E E 11 X 12 Z 13 Z Z Z Z Z 14 Z 15 Z 16
17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.
8 1 1 4 3 0 3 L 1
21 22 23 24 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 Z 19 Z 20 Z 21 0 0 0 0 N 23 Y 24 A 25 X 9 9 9 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Troubleshooting the diesel generator governor motor-operated pot and control circuit
1 1 failed to reveal problems which may have caused or contributed to the erratic loading
1 2 observed during the event. The diesel was started and loaded twice, the PT
1 3 satisfactorily completed, and the diesel generator was returned to service. The
1 4 cause of this event could not be determined; no further action is planned regarding it.

1 5 FACILITY STATUS % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DESCRIPTION (32)
E 28 0 8 9 29 NA B 31 Periodic Test
7 8 9 10 12 13 44 45 46 80
1 6 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36)
E 33 Z 34 NA NA
7 8 9 10 11 44 45 80
1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39)
0 0 0 37 Z 38 NA
7 8 9 10 11 12 13 80
1 8 PERSONNEL INJURIES NUMBER DESCRIPTION (41)
0 0 0 40 NA
7 8 9 10 11 12 80
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION (43)
Z 42
7 8 9 10 80
2 0 PUBLICITY ISSUED DESCRIPTION (45)
N 44 NA
7 8 9 10 80

8404170167 840409
PDR ADOCK 05000324
S PDR

1E22

NRC USE ONLY

NAME OF PREPARER M. J. Pastva, Jr.

PHONE 919-457-9521



Carolina Power & Light Company

34 APR 12 1984

Brunswick Steam Electric Plant

P. O. Box 10429

Southport, NC 28461-0429

April 9, 1984

FILE: B09-13510C
SERIAL: BSEP/84-0907

Mr. James P. O'Reilly, Administrator
U. S. Nuclear Regulatory Commission
Region II, Suite 3100
101 Marietta Street N.W.
Atlanta, GA 30303

BRUNSWICK STEAM ELECTRIC PLANT, UNIT 2
DOCKET NO. 50-324
LICENSE NO. DPR-62
SUPPLEMENT TO LICENSEE EVENT REPORT 2-81-143

Dear Mr. O'Reilly:

In accordance with Section 6.9.1.9b of the Technical Specifications for Brunswick Steam Electric Plant, Unit 2, the enclosed supplemental Licensee Event Report is submitted. The original report fulfilled the requirement for a written report within thirty (30) days of a reportable occurrence and both are in accordance with the format set forth in NUREG-0161, July 1977.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/mcg/LETGG2

Enclosure

cc: Mr. R. G. DeYoung
NRC Document Control Desk

OFFICIAL COPY

LEZZ

111