

POINT BEACH NUCLEAR PLANT
UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH MARCH - 1995

Docket No. 50-301
Unit Name Point Beach, Unit 2
Date May 2, 1995
Completed By M. B. Koudelka
Telephone No. 414/755-6480

No.	Date	Type ¹	Duration (Hours)	Reason ²	Method of Shutting Down Reactor ³	Licensee Event Report No.	System Code ⁴	Component Code ⁵	Cause and Corrective Action To Prevent Recurrence
1	2/25/95	S	122.7	H	4	NA	EG	XXXXXX	The unit was maintained in hot shutdown because of seal oil leakage into the Unit 2 generator. The generator was disassembled. A Westinghouse seal oil expert examined the seal oil package noting no problems with the component. A seal was replaced and an extra drain installed to accommodate excess oil to preclude problems with the generator.
2	3/07/95	F	14.3	A	3	301/95-003-00	HA	MECFUN	A leak in the main turbine EH control oil system caused a main steam stop valve to close. This caused an increase in reactor coolant system temperature. The unit automatically responded by reducing turbine load, followed by an overtemperature differential temperature reactor trip.

¹F: Forced
S: Scheduled

²Reason:
A - Equipment Failure (explain)
B - Maintenance or Testing
C - Refueling
D - Regulatory Restriction
E - Operator Training &
Licensing Exam
F - Administrative
G - Operational Error (explain)
H - Other (explain)

³Method:
1 - Manual
2 - Manual Scram
3 - Automatic Scram
4 - Continuation of
Previous Shutdown
5 - Reduced Load
6 - Other (explain)

⁴Exhibit G - Instructions
for preparation of
data entry sheets
LER file (NUREG-0161)

⁵Exhibit I - Same Source