

LICENSEE EVENT REPORT

CONTROL BLOCK:

- CONTROL BLOCK:

	(1)	(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
1		

<table border="1" style="display: inline-table; vertical-align: middle;"><tr><td>0</td><td>1</td></tr></table>	0	1	A L B R F 3	(2) 0 0 - 0 0 0 0 0 0 0 0 0 0	(3) 4 1 1 1 1 1	(4)	(5)
0	1						
7 8	9 LICENSIE CODE 14	15 LICENSE NUMBER 25	26 LICENSE TYPE 30		57 CAT 58		

REPORT
SOURCE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, while operations personnel were performing a diesel-
0 3 | generator system walkdown, the coupling on unit 3 diesel-generator "C" lube
0 4 | oil pump was found broken. The diesel-generator was made inoperable in
0 5 | accordance with Tech. Spec. 3.9.B(2). It was inoperable from 0900 to 1400 hours.
0 6 | Redundant systems were available and operable. There was no effect on public
0 7 | health and safety.
0 8 |
7 8 9

SYSTEM CODE		CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE				COMP SUBCODE	VALVE SUBCODE						
0	9	E	F	M	E	C	F	U	N	Z	Z				
7	8	9	10	11	12	13	14	15	16	17	18				
EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.							
8	2	0 6 7		0 3		L		0							
21	22	23	24	25	26	27	28	29	30	31	32				
ACTION TAKEN		EFFECT ON PLANT		SHUTDOWN METHOD		HOURS		ATTACHMENT SUBMITTED		NPRD-4 FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER	
C	X	Z	Z	Z		0 0 0 0		Y		N		N		V 1 2 5	
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Cause was deterioration of the coupling spider due to normal service, resulting in

1 1 coupling failure. The lube oil circulating pump Model GV503A is manufactured by

1 2 Viking. The coupling manufacturer is Lovejoy. A new coupling was installed and

1 3 S. I. 4.9.A.1.(a) was performed.

1 4

FACILITY STATUS			% POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	E	23	1	0	0	29	NA	A	31	Operator observation			
ACTIVITY			CONTENT			AMOUNT OF ACTIVITY			LOCATION OF RELEASE					
RELEASED			OF RELEASE											
1	6	Z	C	Z	34	NA			NA					
PERSONNEL EXPOSURES			NUMBER			TYPE			DESCRIPTION					
1	7	0	0	0	37	Z	38	NA						
PERSONNEL INJURIES			NUMBER			DESCRIPTION								
1	8	0	0	0	40	NA								
LOSS OF OR DAMAGE TO FACILITY			TYPE			DESCRIPTION								
1	9	Z	42	NA										
PUBLICITY			ISSUED			DESCRIPTION								
2	0	N	44	8302010283 830121 PDR ADOCK 05000296 S PDR			NRC USE ONLY							

Michael R. Porter

PHONE (205) 729-0790

LER SUPPLEMENTAL INFORMATION

BFRO-50-296 / 82067 Technical Specification Involved 3.9.B.(2)

Reported Under Technical Specification 6.7.2.b.(2) * Date Due NRC 1/24/83

Event Narrative:

Unit 1 was operating normally at 100-percent power; unit 2 was shut down for a refueling outage. Unit 3, the only unit affected by this event, was operating normally at 100-percent power.

During a walkdown inspection of the diesel-generator system by operations personnel, the coupling on unit 3 diesel-generator "C" lube oil circulating pump was discovered broken. In order to prevent possible damage to the diesel engine, the diesel-generator was made inoperable at 0900 hours. [Technical Specification 3.9.B.(2)] Redundant equipment was tested and proved operable per surveillance requirements specified in Technical Specification 3.9.B.(2). The coupling was replaced and the diesel tested, performed satisfactorily, and was declared operable at 1400 hours. The cause of the event was attributed to deterioration of the coupling spider due to normal service leading to failure of the coupling. The lube oil circulating pump, manufactured by Viking, is a Model GV503A and the coupling is manufactured by Lovejoy.

All couplings on remaining diesel-generators will be inspected during the next performance of the semiannual portion of Mechanical Maintenance Instruction 6.

* Previous Similar Events:

None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

*Revision: JRP