

CONTROL BLOCK: | | | | | | | ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

Technical Specifications: Table 3.3.2-1, Item 3a, 6.9.1.9b

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

PHONE: 919-457-9521

LER ATTACHMENT - RO #2-82-143

Facility: Unit No. 2

Event Date: December 20, 1982

This event occurred when the instrument indication of RWCU differential flow indicator, 2-G31-R615, General Electric Model No. 180, went downscale. Three RWCU flow transmitters, 2-G31-FT-N012, N036, and N041, one on the RWCU suction line and one each on the two RWCU discharge lines, feed a RWCU summing circuit, 2-G31-K604. The summing circuit takes the suction flow and compares it with the combined discharge flow to produce a differential flow signal to the RWCU isolation circuits. 2-G31-R615 is a direct reading indicator off one of the two parallel signals from the summer.

This event resulted from partial plugging of the instrument low side sensing line to FT-N041 combined with the remaining RWCU flow transmitters and associated instrumentation being slightly out of calibration. The low side instrument sensing line to FT-N041 was cleared and the RWCU differential flow transmitters, General Electric Model No. 555, and associated instrumentation were calibrated and returned to service. The failure of FT-N041, attributed to line plugging, is considered isolated. No further action regarding this event is required or planned.