

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)
Washington Nuclear Project - Unit 2DOCKET NUMBER (2)
0 5 0 0 0 3 9 7 1 OF 0 2

PAGE (3)

TITLE (4)

Inadvertent Initiation of Control Room Emergency Filtration Units

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)						
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)					
0	3	1	7	8	4	8	4	0	2	4	0	5	0	0	0
0	3	1	7	8	4	8	4	0	2	4	0	5	0	0	0

THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11)

OPERATING MODE (9)	4	20.402(b)	20.405(c)	50.73(a)(2)(iv)	73.71(b)
POWER LEVEL (10)	0 0 0	20.405(a)(1)(i)	50.38(c)(1)	50.73(a)(2)(v)	73.71(c)
		20.405(a)(1)(ii)	50.38(c)(2)	50.73(a)(2)(vi)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
		20.405(a)(1)(iii)	50.73(a)(2)(i)	50.73(a)(2)(vii)(A)	
		20.405(a)(1)(iv)	50.73(a)(2)(ii)	50.73(a)(2)(vii)(B)	
		20.405(a)(1)(v)	50.73(a)(2)(iii)	50.73(a)(2)(x)	

LICENSEE CONTACT FOR THIS LER (12)

NAME
L. D. Kassakatis, Plant Compliance Engineer

TELEPHONE NUMBER

AREA CODE
5 0 9 3 7 7 - 1 5 0 1

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

Ext. 4727

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NPRDS
A	I	L		N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE) ☐ NO ☒

EXPECTED SUBMISSION DATE (15)

MONTH DAY YEAR

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single space typewritten lines) (16)

Initiation of the Control Room Emergency Filtration Units due to the inadvertent de-energization and re-energization of test equipment during instrument calibration. This is a unique event and requires no corrective action other than continued cautioning of personnel.

8404180389 840411
PDR ADOCK 05000397
S PDRJE22
1/1

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104

EXPIRES 8/31/85

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
Washington Nuclear Project - Unit 2	0 5 0 0 0 3 9 7	8 4	— 0 2 4	— 0 0	0 2	OF	0 2

TEXT (If more space is required, use additional NRC Form 366A's) (17)

- a) Power Level - Zero
- b) Plant Mode - 4
- c) Prior to Initial Power Operations

The Control Room Emergency Filtration Units were automatically initiated by a high-high radiation alarm originating from the outside air intake monitors (Equipment Piece Numbers WOA-RIS-31B and 32B). This actuation was immediately determined to have been caused by a Technician inadvertently de-energizing and re-energizing test equipment. During calibration of one of the radiation system monitors (EPN CMS-RIS-27D) the test equipment in use (Hewlett Packard Function Generator Model 3352A) was not completely plugged into a local outlet. The Technician performing the calibration bumped into the power cord, dislodging it from the outlet and immediately reinserted the plug into the outlet. The resultant spike caused the following instruments to give spurious high and high-high radiation alarms:

- WOA-RIS-31B
- WOA-RIS-32B
- CMS-RIS-27D
- CMS-RIS-12-1B
- CMS-RIS-12-3B

The spiking of instruments WOA-RIS-31B and 32B caused the actuation of the engineered safety feature system.

These alarms were promptly reset and the ESF system returned to normal.

This is a unique event and requires no corrective action other than the continuous cautioning of personnel.

Washington Public Power Supply System

P.O. Box 968 3000 George Washington Way Richland, Washington 99352 (509) 372-5000

Docket No. 50-397
April 11, 1984

Document Control Desk
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555


Subject: **NUCLEAR PROJECT NO. 2**
LICENSEE EVENT REPORT NO. 84-024

Dear Sir:

Transmitted herewith is Licensee Event Report No. 84-024 for WNP-2 Plant. This report is submitted in response to the report requirements of Technical Specification Section 6.9.1.7 and discusses the item of noncompliance, corrective action taken, and action taken to preclude recurrence.

This is the follow-up report to the verbal notification given at 0950 hours on March 17, 1984.

Very truly yours,


J. D. Martin (M/D 927M)
WNP-2 Plant Manager

JDM:de

Enclosure:
Licensee Event Report No. 84-024

cc: Mr. John B. Martin, Administrator
Region V, Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
1450 Maria Lane
Walnut Creek, California 94596
Mr. A. D. Toth, NRC Resident Inspector (901A)

IE22
1/1