

LICENSEE EVENT REPORT

U. S. NUCLEAR REGULATORY COMMISSION
UPDATE REPORT
PREVIOUS REPORT DATE: 04-08-81

CONTROL BLOCK:

--	--	--	--	--	--

1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	M	D	C	C	N	2	2	0	0	-	0	0	0	0	0	-	0	0	3	4	1	1	1	1	4			5		
7	8	LICENSEE CODE						14	15	LICENSE NUMBER										25	26	LICENSE TYPE					30	57	CAT		58

CON'T

0 1 7 8
REPORT SOURCE L 6 0 5 0 0 0 3 1 8 7 0 3 0 9 8 1 8 0 1 1 9 8 3 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During Mode 3 operation at 0600 while personnel were exiting the Con-
0 3 | tainment Building via the normal personnel access hatch, both doors were
0 4 | open simultaneously, a degradation of the requirements of T.S. 3.6.1.1
0 5 | and T.S. 3.6.1.3.a. The outer door was shut in about 20 seconds. Also,
0 6 | for about 4 hours on March 7 and about 1.5 hours on March 9, the
0 7 | inner door was failed in a partially open position (T.S. 3.6.1.3.a).
0 8 | The outer door was shut during both events. Similar events: none.

SYSTEM CODE S A 11		CAUSE CODE E 12		CAUSE SUBCODE B 13		COMPONENT CODE P E N E T R 14				COMP. SUBCODE A 15		VALVE SUBCODE Z 16					
EVENT YEAR 8 2		SEQUENTIAL REPORT NO. 0 1 2		OCCURRENCE CODE 0 3		REPORT TYPE X		REVISION NO. 1									
ACTION TAKEN F 18		FUTURE ACTION Z 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22		ATTACHMENT SUBMITTED N 23		NPRD-4 FORM SUB. N 24		PRIME COMP. SUPPLIER A 25		COMPONENT MANUFACTURER C 1 3 0 26	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Airlock mechanism failed due to a broken Cam Follower. An overhaul has

1 1 been performed which includes manufacturer's recommendations for replac-

1 2 ing operating mechanism parts with higher strength replacements. Also,

1 3 the forces acting upon the new parts will be less due to the limited

1 4 free play in the door's mechanism. No further action is required.

7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

FACILITY STATUS (28) % POWER (29) OTHER STATUS (30) METHOD OF DISCOVERY (31) DISCOVERY DESCRIPTION (32)

1 5 G 0 0 0 N/A A Operator Observation

2 3 4 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

ACTIVITY CONTENT
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35)

1 6 2 33 34 N/A

7 8 9 10 11 44

LOCATION OF RELEASE (36)

N/A

45 80

PERSONNEL EXPOSURES										
NUMBER			TYPE	DESCRIPTION						
1	7	0	0	0	(37)	Z	(38)	N/A	(39)	

PERSONNEL INJURIES		NUMBER		DESCRIPTION	
1	8	0	0	0	40 N/A

7		8	9	11		12	60	
		LOSS OF OR DAMAGE TO FACILITY						(43)
		TYPE						DESCRIPTION
1	9	Z	(42)	N/A				

7 8 9 10
 PUBLICITY
 ISSUED DESCRIPTION (45)
 2 0 N (44) N/A
 7 8 9 10
 8302010560 830119
 PDR ADOCK 05000318
 S PDR
 NRC USE ONLY
 68 69 70

NAME OF PREPARER R. L. Wenderlich/P. J. Weir

PHONE: 301-269-4776/4871