

LICENSEE EVENT REPORT

U. S. NUCLEAR REGULATORY COMMISSION

Update Report

Previous Report Date: 1/5/83

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	N	C	B	E	P	1	2	0	0	-	0	0	0	0	-	0	0	3	4	1	1	1	1	4	5
7	8	LICENSEE CODE						14	15	LICENSE NUMBER						25	26	LICENSE TYPE				30	57	CAT	58	

CON'T

0 1
7 8

REPORT SOURCE L 6 0 5 0 - 0 3 2 5 7 0 3 2 9 8 2 8 0 1 1 7 8 3 9
60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During plant operation, a comparison of RTGB indications of suppression chamber water
0 3 | level revealed that RTGB instrument, 1-CAC-LR-2602, indicated a level of -31.5" while
0 4 | RTGB instrument, 1-CAC-LI-2601-3, indicated a level of -28". A check of the local
0 5 | level indicator determined the actual level to be -28". This event did not affect
0 6 | the health and safety of the public.
0 7 |
0 8 | Technical Specifications 3.3.5.3, 6.9.1.9b

SYSTEM CODE I E 11		CAUSE CODE B 12		CAUSE SUBCODE A 13		COMPONENT CODE I N S T R U 14		COMP. SUBCODE T 15		VALVE SUBCODE Z 16							
EVENT YEAR 8 2 21 22		SEQUENTIAL REPORT NO. 0 4 4 24 26		OCCURRENCE CODE 0 3 28 29		REPORT TYPE L 30		REVISION NO. 2 32									
ACTION TAKEN X 18		FUTURE ACTION C 19		EFFECT ON PLANT Z 20		SHUTDOWN METHOD Z 21		HOURS 0 0 0 0 22 37 40		ATTACHMENT SUBMITTED Y 23		NPRD-4 FORM 37B. Y 24		PRIME COMP. SUPPLIER N 25		COMPONENT MANUFACTURER B 0 4 C 26 44 47	

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 This event resulted from a change in trickle flow to the wet reference leg of the 2602
1 1 recorder transmitter, 1-CAC-LT-2602, Model No. BQ15221. The trickle flow change
1 2 caused the transmitter to sense an incorrect differential pressure. The trickle flow
1 3 to the transmitter was properly established, and the transmitter was calibrated and
1 4 returned to service.

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	5	E	28	0	5	9	29	NA	Operator Surveillance
ACTIVITY CONTENT		RELEASED OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
1	6	Z	33	Z	34	NA			
PERSONNEL EXPOSURES		NUMBER		TYPE		DESCRIPTION			
1	7	0	0	0	37	Z	38	NA	
PERSONNEL INJURIES		NUMBER		DESCRIPTION		8302010619 830117			
1	8	0	0	0	40		PDR ADOCK 050G0325		
LOSS OF OR DAMAGE TO FACILITY		TYPE		DESCRIPTION		S			
1	9	Z	42			NA			
PUBLICITY		ISSUED		DESCRIPTION		NA		NRC USE ONLY	
2	0	N	44						

NAME OF PREPARER M. J. Pastva, Jr.

PHONE: (919) 457-9521

LER ATTACHMENT - RO #1-82-44

Facility: BSEP Unit No. 1

Event Date: March 29, 1982

As a result of an event involving this instrumentation on Unit No. 1, as reported in LER 1-81-07 and a post-TMI requirement, plant modification packages (1-80-79 and 80-016 for Unit No. 1 and 2-80-78 and 80-017 for Unit No. 2) have been developed. These modifications will install condensing pots in the reference legs of these instruments in order to increase their accuracy and reliability and remove the requirement to have flow in their reference legs to ensure they are full.