

## LICENSEE EVENT REPORT

CONTROL BLOCK: 

|  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|
|  |  |  |  |  |  |  |
|--|--|--|--|--|--|--|

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

|   |   |   |               |   |   |   |   |    |    |                |   |   |   |   |   |   |   |   |   |    |    |              |   |   |   |   |    |    |     |  |    |
|---|---|---|---------------|---|---|---|---|----|----|----------------|---|---|---|---|---|---|---|---|---|----|----|--------------|---|---|---|---|----|----|-----|--|----|
| 0 | 1 | T | N             | S | N | P | 1 | 2  | 0  | 0              | - | 0 | 0 | 0 | 0 | 0 | - | 0 | 0 | 3  | 4  | 1            | 1 | 1 | 1 | 4 |    |    | S   |  |    |
| 7 | 8 | 9 | LICENSEE CODE |   |   |   |   | 14 | 15 | LICENSE NUMBER |   |   |   |   |   |   |   |   |   | 25 | 26 | LICENSE TYPE |   |   |   |   | 30 | 31 | CAT |  | 36 |

CON'T

REPORT SOURCE: 01 605000327712318280128839  
69 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 With unit 1 in mode 5 and unit 2 in mode 2 (1.5% power) at 1143 CST on 12/31/82

03 the auxiliary building ventilation radiation monitor (RM-90-101) was declared

0 4 | inoperable due to loss of adequate flow. This event required entry into action

05 | statements 41, 42, and 44 of LCO 3.3.3.10. There was no effect upon public

0 6 health and safety. Previous occurrences - nine (SQRO-50-327/80053, 80004, 80021

07 80167, 80148, 80043, 80030, 80050, and 80024).

7 8 9

0 9 M B 11 E 12 E 13 I N S T R U 14 S 15 Z 16

(17) LER/RO REPORT NUMBER [ 8 | 2 ]  
 21. 22. 23. [ — ]  
 SEQUENTIAL REPORT NO. [ 1 | 4 | 4 ]  
 24. 25. 26. [ / ]  
 OCCURRENCE CODE [ 0 | 3 ]  
 28. 29. 30. [ L ]  
 REPORT TYPE [ — ]  
 31. 32. 33. [ 0 ]  
 REVISION NO. [ 0 ]  
 34. 35. 36.

| ACTION TAKEN |    | FUTURE ACTION |    | EFFECT ON PLANT |    | SHUTDOWN METHOD |    | HOURS |    |    |    | ATTACHMENT SUBMITTED |    | NPRD-4 FORM SUB. |    | PRIME COMP. SUPPLIER |    | COMPONENT MANUFACTURER |    |    |
|--------------|----|---------------|----|-----------------|----|-----------------|----|-------|----|----|----|----------------------|----|------------------|----|----------------------|----|------------------------|----|----|
| E            | 18 | Z             | 19 | Z               | 20 | Z               | 21 | 0     | 0  | 0  | 0  | N                    | 23 | N                | 24 | L                    | 25 | G                      | 0  | 6  |
| 33           | 34 | 35            | 36 | 37              | 38 | 39              | 40 | 41    | 42 | 43 | 44 | 45                   | 46 | 47               | 48 | 49                   | 50 | 51                     | 52 | 53 |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (21)

10 Investigation revealed that the monitor pump motor starter switch had tripped.

11 Also, the monitor flow switches were found out of calibration. The pump motor

1 2 starter switch was reset and the pump started. Also the flow switches were re-

1 3 [ ] calibrated and the monitor RM-90-101 returned to service on 01/03/83. The cause

1 4 | for the overload which tripped motor starter switch is unknown. No further action  
8 9 | is planned at this time.

1 5 G 28 0 0 0 29 NA 30 31 B 32 Operator observation.

| ACTIVITY |   | CONTENT    |    |                    |    |                          |
|----------|---|------------|----|--------------------|----|--------------------------|
| RELEASED |   | OF RELEASE |    | AMOUNT OF ACTIVITY |    |                          |
| 6        | Z | (33)       | Z  | (34)               | NA | LOCATION OF RELEASE (36) |
| R        | Q | 10         | 10 | 10                 | NA |                          |

| PERSONNEL EXPOSURES |   |   |      |             |   |    |    |  |  |
|---------------------|---|---|------|-------------|---|----|----|--|--|
| NUMBER              |   |   | TYPE | DESCRIPTION |   |    |    |  |  |
| 7                   | 0 | 0 | 0    | 17          | Z | 38 | NA |  |  |

| PERSONNEL INJURIES |             |
|--------------------|-------------|
| NUMBER             | DESCRIPTION |
| 8 0 0 0            | 41 NA       |

| 9                             | 11          | 12      |      |
|-------------------------------|-------------|---------|------|
| LOSS OF OR DAMAGE TO FACILITY |             |         | (43) |
| TYPE                          | DESCRIPTION |         |      |
| 9                             | Z           | (42) NA |      |

8 9 10  
PUBLICITY  
ISSUED DESCRIPTION (45)  
0 N (44) NA  
8302030439 830128  
PDR ADDCK 05000327  
S PDR  
NRC USE ONLY

 Springer

NRC USE ONLY

Name of Preparer: H. R. Rogers /M. R. Harding

Phone: (615) 751-0349