

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)0 1 A L B R F 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 37 CAT 38

CONT

0 1 REPORT SOURCE 1 6 0 5 0 0 0 2 5 9 7 1 2 2 9 8 2 8 0 1 2 3 8 3 9
7 8 DOCKET NUMBER 60 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation on unit 1, 1-RM-90-265 failed in the downscale tripped

0 3 condition. T. S. 3.2.D(b) permits a 7-day LCO for this condition. The

0 4 redundant offgas post-treatment radiation monitor (1-RM-90-266) was operable.

0 5 An offgas isolation occurs when both channels are tripped. There was no

0 6 adverse effect on the health or safety of the public.

0 7

0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP SUBCODE VALVE SUBCODE

M C 11 E 12 A 13 I N S T R U 14 X 15 Z 16

17 LER/RO REPORT NUMBER EVENT YEAR SEQUENTIAL REPORT NO. OCCURRENCE CODE REPORT TYPE REVISION NO.

8 2 1 0 1 0 3 1 0

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRO-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER

A 18 Z 19 Z 20 Z 21 0 0 0 0 0 Y 23 Y 24 L 25 G 0 8 0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 This event was caused by the failure of the +15-volt regulator (G. E. #194X363G1).

1 1 The regulator was replaced and the monitor was returned to service. This was

1 2 a random event, and no further recurrence control is required.

1 3

1 4

1 5 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION

E 28 1 0 0 29 NA A 31 Operator observed

ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

Z 33 Z 34 NA NA

PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION

0 0 0 37 38 NA

PERSONNEL INJURIES NUMBER DESCRIPTION

0 0 0 40 NA

LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION

Z 42 NA

PUBLICITY ISSUED DESCRIPTION

N 44

8302030577 830128
PDR ADOCK 05000259
S PDR

NRC USE ONLY

NAME OF PREPARER George T. Chambers

PHONE (205) 729-0841

LER SUPPLEMENTAL INFORMATION

BFRO-50- 259 / 82101 Technical Specification Involved 3.2.D(b)

Reported Under Technical Specification 6.7.2.b.2 * Date Due NRC 1/29/83

Event Narrative:

Unit 1 was operating at 100-percent power; unit 2 was in a refueling outage; and unit 3 was operating at 99.8-percent power. At 1940 hours, the unit 1 offgas post-treatment radiation monitor (1-RM-90-265) failed in the downscale tripped condition [Technical Specification 3.2.D(b)]. Plant instrument mechanics discovered that the +15-volt regulator had failed. The regulator was replaced and the monitor was returned to service at 2145 hours. There was no adverse effect on the health or safety of the public. The redundant offgas post-treatment radiation monitor (1-RM-90-266) was operable. This was a random event and no further recurrence control is required.

Previous Similar Events:

None

Retention: Period - Lifetime; Responsibility - Document Control Supervisor

Revision: JRP