

LICENSEE EVENT REPORT

U S NUCLEAR REGULATORY COMMISSION
UPDATE REPORT - PREVIOUS REPORT
DATE 07/15/82

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 C T M N S 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

CON'T

01 REPORT SOURCE L 6 0 5 0 0 0 3 3 6 7 0 6 1 7 8 2 8 0 3 2 9 8 4 9
7 8 9 14 15 25 26 30 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During a containment entry for routine surveillance a leak was noticed in the

03 safety injection test header at two places upstream of relief valve 2-SI-466.

04 There are no probable consequences as a result of this event. Similar events:

05 81-022, 81-2, 80-27, 77-3, 77-10.

06

07

08

09 SYSTEM CODE S F 11 CAUSE CODE B 12 CAUSE SUBCODE A 13 COMPONENT CODE P I P E X X 14 COMP SUBCODE A 15 VALVE SUBCODE Z 16

17 LER NO REPORT NUMBER 8 2 21 22 0 2 3 23 24 0 3 25 26 X 27 1 28 29

ACTION TAKEN B 18 F 19 EFFECT ON PLANT Z 20 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED N 23 NRC-4 FORM 508 Y 24 PRIME COMP SUPPLIER A 25 COMPONENT MANUFACTURER B 1 3 0 26

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Pressure waves from cycling of relief valve 2-SI-466 causes abnormal stresses in

11 the safety injection test header. The cracks were weld repaired and a section

12 of pipe was replaced. A design change has been recommended; due to parts

13 availability it will not be implemented until the next refuel outage.

14 Operations procedures have been revised in the interim.

15 FACILITY STATUS E 28 % POWER 1 0 0 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Operator Observation 32

16 ACTIVITY RELEASED Z 33 CONTENT Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36

17 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39

18 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41

19 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43

20 PUBLICITY ISSUED N 44 DESCRIPTION NA 45

8404240172 840329
PDR ADOCK 05000336
S PDR

NRC USE ONLY

NAME OF PREPARER Steve Stadnick

PHONE (203) 447-1791 X4427

NORTHEAST UTILITIES



THE CONNECTICUT LIGHT AND POWER COMPANY
WESTERN MASSACHUSETTS ELECTRIC COMPANY
HOLYOKE WATER POWER COMPANY
NORTHEAST UTILITIES SERVICE COMPANY
NORTHEAST NUCLEAR ENERGY COMPANY

General Offices • Selden Street, Berlin, Connecticut

P.O. BOX 270
HARTFORD, CONNECTICUT 06141-0270
(203) 666-6911

March 29, 1984
MP-5912

Dr. Thomas E. Murley
Regional Administrator, Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Reference: Facility Operating License No. DPR-65
Docket No. 50-336
Reportable Occurrence RO 50-336/82-23/03X-01

Dear Dr. Murley:

This letter forwards the update Licensee Event Report 82-23 concerning operation of the unit with a limiting condition for operation in a less conservative condition than is established in the Technical Specifications. An additional three copies of the report are enclosed.

Yours truly,

NORTHEAST NUCLEAR ENERGY COMPANY

E. J. Mroczka
Station Superintendent
Millstone Nuclear Power Station

EJM/SLS:mo

Attachment: LER RO 82-23/03X-01

cc: Director, Office of Inspection and Enforcement, Washington, D. C. (30)
Director, Office of Management Information and Program Control,
Washington, D. C. (3)
U. S. Nuclear Regulatory Commission, c/o Document Management Branch,
Washington, D. C. 20555

IE22
11