

LER 76-11/1T  
LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 NYREG 14  
 LICENSE NUMBER: 00-000000-00 25  
 LICENSE TYPE: 41111 30  
 EVENT TYPE: 01 32  
 CATEGORY: 01 CONT 57 58  
 REPORT TYPE: T 59  
 REPORT SOURCE: L 60  
 DOCKET NUMBER: 050-0244 68  
 EVENT DATE: 030876 74  
 REPORT DATE: 031976 80

EVENT DESCRIPTION

02 During flow test of control room ventilation system in preparation for charcoal filter  
 03 efficiency test there was zero flow indicated for cleanup filtering path, designed for  
 04 25% total system flow. Investigation showed filter inlet damper stroked closed when  
 05 system was transferred to accident mode operation. Drive piston was remounted to  
 06 obtain correct damper orientation. (Reportable Occurrence 76-11, 14-day)

SYSTEM CODE: 07 SG 10  
 CAUSE CODE: A 11  
 COMPONENT CODE: ZZZZZZ 17  
 PRIME COMPONENT SUPPLIER: Z 43  
 COMPONENT MANUFACTURER: Z999 47  
 VIOLATION: N 48

CAUSE DESCRIPTION

08 Drive piston was improperly mounted during construction. Deficiency was identified  
 09 by commercial tester in preoperational testing; follow-up corrective action did not take  
 10 place. Periodic surveillance of the Radiation Monitoring (cont'd. on attached sheet)

FACILITY STATUS: H 9  
 % POWER: 000 10 12 13  
 OTHER STATUS: NA 44  
 METHOD OF DISCOVERY: b 45  
 DISCOVERY DESCRIPTION: NA 46

FORM OF ACTIVITY RELEASED: Z 9  
 CONTENT OF RELEASE: Z 10  
 AMOUNT OF ACTIVITY: NA 44  
 LOCATION OF RELEASE: NA 45

PERSONNEL EXPOSURES

13 NUMBER: 000 11  
 TYPE: Z 12  
 DESCRIPTION: NA 13

PERSONNEL INJURIES

14 NUMBER: 000 11  
 DESCRIPTION: NA 12

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

16 TYPE: Z 9  
 DESCRIPTION: NA 10

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19

8304050046 760319  
 PDR ADDCK 05000244  
 S PDR

NAME: Charles V. Hartlieb

PHONE: 716/546-2700, Ext. 291-216

Licensee Event Report  
Reportable Occurrence 50-244/76-11

Cause Description (cont'd.)

System and associated automatic actions has included observance of the movement of the drivers for this system; the drivers had always repositioned the dampers to the position which was assumed to be correct. Under the present Q.A. program, modification control provides means of proper acceptance of new plant safety related features.



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 548-2700

March 19, 1976

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406



Subject: Reportable Occurrence 76-11 (14-day report), Control Room  
charcoal filter damper  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.9.2a, the attached report of Reportable Occurrence 76-11, 14-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

*L.D. White, Jr.*  
L. D. White, Jr.

Attachment

cc: Mr. John G. Davis (40)  
Mr. William G. McDonald (3)

2908