

R

ROCHESTER GAS AND ELECTRIC CORPORATION • 69 EAST AVENUE, ROCHESTER, N.Y. 14604

TELEPHONE  
526 2100

Ginna Station  
March 9, 1976

7 d E

Mr. James P. O'Reilly  
U. S. Nuclear Regulatory Commission  
Directorate of Regulatory Operations  
Region 1  
631 Park Ave.  
King of Prussia, Pennsylvania 19406

SUBJECT: Reportable Occurrence #76-11: Control Room Charcoal Filter Damper  
Improperly Positioned

Dear Mr. O'Reilly:

This is to confirm my phone call to Mr. Bert Davis on March 8, 1976, to report the improper positioning of one of the two dampers for the control room charcoal filter system.

While conducting a flow check on the control room charcoal filter system on 3-8-76, it was discovered that one of the two dampers that controls 25% of the control room air flow through the charcoal filters during a radiation emergency was in the wrong position. This condition allowed one of the two dampers to always be closed so that the recirculation of 25% of the control room air through the charcoal filter was not possible.

A trouble card was issued and work is being done today to correct the problem.

Very truly yours,

*Charles E. Platt*

Charles E. Platt  
Superintendent

EP:d1

c: Mr. G. J. Swarthout, EG&E Corp.  
Mr. L. D. White, Jr., EG&E Corp.

8304050051 760319  
PDR ADDCK 05000244  
S PDR