

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 I L D R S 2										LICENSE NUMBER 0 0 - 0 0 0 0 0 - 0 0										LICENSE TYPE H 1 1 1 1					EVENT TYPE 0 3																								
CATEGORY 01 CON'T										REPORT TYPE L					REPORT SOURCE L					DOCKET NUMBER 0 5 0 - 0 2 3 7										EVENT DATE 0 5 2 7 7 6										REPORT DATE 0 6 2 3 7 6									

EVENT DESCRIPTION

02 DURING UNIT-2 DRYWELL INERTING, THE NITROGEN STORAGE TANK LEVEL DROPPED TO 54																																																																															
03 INCHES. TANK LEVEL REMAINED BELOW 60 INCHES APPROXIMATELY TWO (2) HOURS BEFORE																																																																															
04 ADDITIONAL NITROGEN WAS DELIVERED. NITROGEN LEVEL WAS THEN PROMPTLY RESTORED																																																																															
05 TO WELL ABOVE THE MINIMUM LIMIT (TECH SPEC 3.7.A.6.B). THIS IS A REACTIVE																																																																															
06 OCCURRENCE. (50-237/1976-35)																																																																															

SYSTEM CODE 07 S E										CAUSE CODE F										COMPONENT CODE X X X X X X										PRIME COMPONENT SUPPLIER Z										COMPONENT MANUFACTURER Z 9 9 9										VIOLATION N									
---	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

CAUSE DESCRIPTION

08 THE EVENT WAS CAUSED BY AN UNANTICIPATED DELAY IN THE DELIVERY OF THE NITROGEN. IN ORDER																																																																															
09 TO MAINTAIN THE LESS THAN 4% OXYGEN CONCENTRATION AND TORUS/DRYWELL 1# DO REQUIRE-																																																																															
10 MENTS, WHICH TOOK PRECEDENCE, THE NITROGEN STORAGE TANK LEVEL WAS ALLOWED TO TEM-																																																																															

FACILITY STATUS 11 										% POWER 0 2 5										OTHER STATUS NA										METHOD OF DISCOVERY B										DISCOVERY DESCRIPTION NA									
FORM OF ACTIVITY RELEASED 12 Z										CONTENT OF RELEASE Z										AMOUNT OF ACTIVITY NA										LOCATION OF RELEASE NA																			

PERSONNEL EXPOSURES

NUMBER 13 0 0 0										TYPE Z										DESCRIPTION NA									
--	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--

PERSONNEL INJURIES

NUMBER 14 0 0 0										DESCRIPTION NA									
--	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--

OFFSITE CONSEQUENCES

15 NA																																																																															
---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

LOSS OR DAMAGE TO FACILITY

TYPE 16 Z										DESCRIPTION NA									
--	--	--	--	--	--	--	--	--	--	---	--	--	--	--	--	--	--	--	--

PUBLICITY

17 NA																																																																															
---	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--

8304050082 760623
PDR ADOCK 05000237
S PDR

ADDITIONAL FACTORS CAUSE DESCRIPTION (CONT.)

18 TEMPORARILY DROP BELOW 60 INCHES. THE REQUIRED NITROGEN LEVEL WAS REGAINED WITHIN																																																																															
19 THE SPECIFIED TIME LIMIT.																																																																															



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

BBS Ltr. # 76-477

June 24, 1976

Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Enclosed please find Reportable Occurrence Report number 50-237/1976-35.
This report is being submitted to your office in accordance with the Dresden
Nuclear Power Station Technical Specifications, Section 6.6.B.

Arthur M. Roberts
for B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:jo

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

6588

COPY SENT REGION III