

CONTROL BLOCK:

1	2	3	4	5	6
---	---	---	---	---	---

LICENSEE NAME					LICENSE NUMBER										LICENSE TYPE					EVENT TYPE					
01	N	Y	R	E	G	1	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3	
7	8	9				14	15											25	26				30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE				REPORT DATE										
01	CON'T		L	L	0	5	0	-	0	2	4	4	0	2	0	6	7	6	0	2	1	9	7	6
7	8	57	58	59	60	61							68	69					74	75				80

02 During surveillance testing of undervoltage relays, undervoltage device 274/11B failed
7 8 9 80
03 to drop to de-energized position after undervoltage signal was simulated. Redundant
7 8 9 80
04 relay 273/11B operated properly. Three previous occurrences of this type were reported
7 8 9 80
05 on 6/8/73, 12/13/74 and 8/5/75. All 4 u.v. relays were field stripped to clean
7 8 9 80
06 plungers and retested satisfactorily. (Reportable Occurrence 50-244/76-06, 30-day)
7 8 9 80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION			
0	7	I A	E	R	E	L	A	Y	X	N	W	1	2	0	N
7	8	9	10	11	12				17	43	44			47	48

08	The u.v. relay plunger malfunction was due to buildup of bushing deposits on plunger	
7	8	9
09	shaft. The device is a Westinghouse type SV 75-150V ac undervoltage relay. New	80
7	8	9
10	type relays for this application have been tested for (cont'd. under Additional Factors)	80
7	8	9

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
1	1	0	0	0	NA		b	NA		
7	8	9	10	11	12	13	14	15	16	17

FORM OF ACTIVITY RELEASED: 1 2
CONTENT OF RELEASE: 2
AMOUNT OF ACTIVITY: NA
LOCATION OF RELEASE: NA

NUMBER			TYPE	DESCRIPTION
13	000	2	NA	

NUMBER				DESCRIPTION	
1	4	0	0	0	NA

1	5	NA						
7	8	9						
LOSS OR DAMAGE TO FACILITY								80

TYPE			DESCRIPTION
18	2		NA

17 NA S PDR ADUCK 05000244 PDR 7 8 9 80

1a (cont'd. from Cause Description) reliability and duly approved for installation during
7 8 9 80

19. the present refueling outage.

PHONE: 716/546-2700, ext. 291-216




ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

February 19, 1976

Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406




Subject: Reportable Occurrence 76-06 (30-day report), Malfunction of
Undervoltage Relay during surveillance test
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.9.2b, the attached report of Reportable Occurrence 76-06, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,


L. D. White, Jr.

Attachment

cc: Mr. John G. Davis (30)
Mr. William G. McDonald (3)

1798