

# LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 N Y R E G I 14  
 LICENSE NUMBER: 15 0 0 - 0 0 0 0 0 0 - 0 0 25  
 LICENSE TYPE: 26 4 1 1 1 1 30  
 EVENT TYPE: 31 0 3 32

CATEGORY: 01 CON T 57  
 REPORT TYPE: L 58  
 REPORT SOURCE: L 59  
 DOCKET NUMBER: 60 0 5 0 - 0 2 4 4 68  
 EVENT DATE: 69 0 1 1 2 7 6 74  
 REPORT DATE: 75 0 2 0 6 7 6 80

## EVENT DESCRIPTION

02 During normal rounds at cold shutdown operator noticed "B" component cooling (cc) pump  
 03 was noisy. Both cc pumps were running. The "B" pump was stopped and the coupling  
 04 was found to be damaged, with two of the coupling bolts failed. This is the first such  
 05 occurrence. The coupling was repaired, motor realigned and the pump was returned to  
 06 service. (Reportable Occurrence 76-02, 30-day)

SYSTEM CODE: 07 W B 10  
 CAUSE CODE: E 11  
 COMPONENT CODE: M E C F U N 17  
 PRIME COMPONENT SUPPLIER: N 43  
 COMPONENT MANUFACTURER: X 9 9 9 47  
 VIOLATION: N 48

## CAUSE DESCRIPTION

08 The coupling began to fail after two coupling bolts became loose. PORC determined that  
 09 this was random failure and further action to prevent recurrence was not necessary.  
 10 The coupling is a Thomas Coupling Division dry type model (cont'd. under Additional Factors)

FACILITY STATUS: 11 G 9  
 % POWER: 0 0 0 12  
 OTHER STATUS: NA 13  
 METHOD OF DISCOVERY: b 45  
 DISCOVERY DESCRIPTION: NA 46

FORM OF ACTIVITY RELEASED: 12 Z 9  
 CONTENT OF RELEASE: Z 10  
 AMOUNT OF ACTIVITY: NA 11  
 LOCATION OF RELEASE: NA 12

## PERSONNEL EXPOSURES

13 0 0 0 11  
 TYPE: Z 12  
 DESCRIPTION: NA 13

## PERSONNEL INJURIES

14 0 0 0 11  
 DESCRIPTION: NA 12

## OFFSITE CONSEQUENCES

15 NA 12

## LOSS OR DAMAGE TO FACILITY

16 Z 10  
 DESCRIPTION: NA 11

## PUBLICITY

17 NA 12

## ADDITIONAL FACTORS

18 (cont'd. from Cause Description) DBZ 226 for 2-1/8" shaft to 2-3/8" shaft.

19 12

NAME: J. C. Noon

PHONE: 716/546-2700, ext. 291-215



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2700

February 6, 1976



Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 76-02 (30-day report), Component Cooling  
Pump coupling failure.  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.9.2b, the attached report of Reportable Occurrence 76-02, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

L. D. White, Jr.

Attachment

cc: Mr. John G. Davis (30)  
Mr. William G. McDonald (3)

1361