



Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003



December 3, 1973

Re: Indian Point Unit No. 2
Facility Operating
License DPR-26
A.O. 3-2-16 50-247

Mr. John F. O'Leary
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. O'Leary:

The following report is provided pursuant to the requirements of Section 6.12.2(a) of the Technical Specifications of Facility Operating License DPR-26.

On November 18, 1973, following an analysis of the results of periodic tests and calibration checks relating to pressurizer pressure it was found that the setting for one of the three bistables associated with low pressurizer pressure safety injection was below that required by Item 3 in Table 3-1 of the Technical Specifications. At the time of these periodic tests and calibration checks, the reactor was in the cold shutdown condition for maintenance work.

The bistable that had an erroneous setting is part of a two-out-of-three logic system which provides for a safety injection signal on coincident low pressurizer pressure and low pressurizer level. The other two bistables were operating correctly. The channel associated with this device was recalibrated and retested satisfactorily.

Safety implications of this occurrence are considered to be slight since the remaining two channels of the two-out-of-three actuation logic were properly set and would have functioned if required. Investigations into the reason for the low setting have not as yet yielded a definite cause and are being continued.

Very truly yours,

Warren R. Cobean, Jr.
Warren R. Cobean, Jr.,
Manager, Nuclear Power
Generation

8304050153 731203
PDR ADOCK 05000247
S PDR

cc: James P. O'Reilly

COPY SENT REGION 8700