

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, NY 10003

November 19, 1973

Re: Indian Point Unit No. 2
Facility Operating License
DPR-26
A.O. 3-2-16

Mr. James P. O'Reilly, Director
Regulatory Operations, Region I
U. S. Atomic Energy Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. O'Reilly,

The following report of Abnormal Occurrence No. 3-2-16 is provided pursuant to the requirements of Section 6.12.2(a) of the Technical Specifications to Facility Operating License No. DPR-26.

On November 16, 1973 an analysis of the results of periodic tests and calibration checks relating to pressurizer pressure indicated that the setting for one of the three bistables associated with low pressurizer pressure safety injection was below that required by Item 3 in Table 3-1 of the Technical Specifications. At the time of these periodic tests and calibration checks the reactor was in the cold shutdown condition for maintenance work.

The particular bistable device is part of a two out of three logic system which provides for a safety injection signal on coincidence of low pressurizer pressure and low pressurizer level. The other two bistables of the system were found to be operating correctly. The channel associated with this device was recalibrated and retested satisfactorily.

Mr. Don Johnson of your office was notified of this occurrence by Mr. John Makepeace by telephone on November 16, 1973.

Very truly yours,

8304050158 731203
PDR ADDCK 05000247
S PDR

Warren R. Cobean
Warren R. Cobean, Jr.
Manager, Nuclear Power
Generation

cc: Mr. John E. O'Leary

Handwritten: 50-249