

# LICENSEE EVENT REPORT

CONTROL BLOCK: 1           6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME														LICENSE NUMBER										LICENSE TYPE					EVENT TYPE																									
01	N	Y	R	E	G	1									0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3																						
7	8	9				14	15									25	26				30	31	32																															
CATEGORY														REPORT TYPE		REPORT SOURCE		DOCKET NUMBER										EVENT DATE					REPORT DATE																					
01	CON'T															L	L	0										5	0	-	0	2	4	4	0					1	1	1	7	6	0					2	0	6	7	6
7	8														57	58	59	60	61									68	69						74	75						81	82											

EVENT DESCRIPTION

02	During surveillance test prior to heatup CV purge supply and exhaust valves leaked																																																																															
7	8	9																																																																														80
03	excessively. Rubber seat adjustment shoes were realigned and leak rates returned to																																																																															
7	8	9																																																																														80
04	acceptable levels. Excessive leakage from between the purge exhaust valves was																																																																															
7	8	9																																																																														80
05	reported on February 14, 1974 and November 19, 1974. (Reportable Occurrence 76-01,																																																																															
7	8	9																																																																														80
06	30-day)																																																																															
7	8	9																																																																														80

SYSTEM CODE										CAUSE CODE										COMPONENT CODE										PRIME COMPONENT SUPPLIER										COMPONENT MANUFACTURER										VIOLATION									
07	S	D								F										V	A	L	V	E	X						A						P	3	4	0						N													
7	8	9	10	11											12	13	14	15	16	17	43	44	45	46	47	48																																	

CAUSE DESCRIPTION

08	Possible cause is low ambient temperature during shutdown. It has been found that leak																																																																															
7	8	9																																																																														80
09	age checks and adjustments have been necessary after extended operation of purge																																																																															
7	8	9																																																																														80
10	system; the valves have always performed satisfactorily(cont'd. under Additional Factors)																																																																															
7	8	9																																																																														80

FACILITY STATUS										% POWER										OTHER STATUS										METHOD OF DISCOVERY										DISCOVERY DESCRIPTION													
11	G								0	0	0								NA						b						NA																						
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60
FORM OF ACTIVITY RELEASED										CONTENT OF RELEASE										AMOUNT OF ACTIVITY										LOCATION OF RELEASE																							
12	Z								Z								NA						NA																														
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60

PERSONNEL EXPOSURES

NUMBER										TYPE										DESCRIPTION																																	
13	0	0	0							Z										NA																																	
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60

PERSONNEL INJURIES

NUMBER										DESCRIPTION																																											
14	0	0	0							NA																																											
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60

OFFSITE CONSEQUENCES

15	NA																																																										
7	8	9																																																									60

LOSS OR DAMAGE TO FACILITY

TYPE										DESCRIPTION																																											
16	Z										NA																																										
7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48	49	50	51	52	53	54	55	56	57	58	59	60

PUBLICITY

17	NA																																																										
7	8	9																																																									60


8304050160 760206  
PDR ADOCK 05000244  
S PDR

ADDITIONAL FACTORS

18	(cont'd. from Cause Description) during power operation. An investigation for replace-																																																																															
7	8	9																																																																														80
19	ment seat material has been initiated. These are Henry Pratt 48" butterfly valves.																																																																															
7	8	9																																																																														80

NAME: I. C. Noon

PHONE: 716/546-2700, ext. 291-215



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2701

February 6, 1976

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406



Subject: Reportable Occurrence 76-01 (30-day report), Containment  
Purge Supply and Exhaust Valves excessive leak rates  
during testing.  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.9.2b, the attached report of Reportable Occurrence 76-01, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

*L. D. White, Jr.*  
L. D. White, Jr.

Attachment

cc: Mr. John G. Davis (30)  
Mr. William G. McDonald (3)