

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 01 N Y R E G 1 14
 LICENSE NUMBER: 00-000000-00 25
 LICENSE TYPE: 41111 30
 EVENT TYPE: 03 32
 CATEGORY: 01 CON'T 57 58
 REPORT TYPE: L 59
 REPORT SOURCE: L 60
 DOCKET NUMBER: 050-0244 68
 EVENT DATE: 112075 74
 REPORT DATE: 121575 80

[illegible]

EVENT DESCRIPTION		DATE	TIME	REPORTED BY	STATUS
02	During inspection round, a pinhole leak was noted in a 3/4" socket weld of the "B"	7	8	9	80
03	charging pump discharge drain line. The two other charging pumps were operable. The	7	8	9	80
04	affected pump was immediately isolated. The leak was repaired per approved mainte-	7	8	9	80
05	nance and welding procedures. PORC reviewed the event and the corrective action	7	8	9	80
06	taken: no further corrective action was necessary. (Reportable Occurrence 75-11,30-day)	7	8	9	80
PRIME					

CAUSE DESCRIPTION

08 The cause of the leak was formation of a small void during TIG welding. 80

7 8 9

09 80

7 8 9

10 80

7 8 9

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	100		NA		b		NA	
7	8	9	10	11	12	13	44	45	46
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12	M	M		Not discernible		Auxiliary Building vent to atmosphere			
7	8	9	10	11	12	13	44	45	46

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	Z	NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION
1	4	0	0	NA

OFFSITE CONSEQUENCES

15 There was no discernible increase in either release rate or leakage rate.

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	2	NA

PUBLICITY

17	NA	80
----	----	----

ADDITIONAL FACTORS

18 NA S PDR

7 8 9

NAME: _____

J. C. Noon

PHONE: 716/546-2700, ext. 291-214

GPO CEN-663