

LER 76-27/3L
LICENSEE EVENT REPORT

CONTROL BLOCK:

--	--	--	--	--	--

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME:

01	N	Y	R	E	G	1
----	---	---	---	---	---	---

 7 8 9 14
LICENSE NUMBER:

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 15 25
LICENSE TYPE:

4	1	1	1	1
---	---	---	---	---

 26 30
EVENT TYPE:

0	3
---	---

 31 32
CATEGORY:

01	CONT
----	------

 57 58
REPORT TYPE:

L

 59
REPORT SOURCE:

L

 60
DOCKET NUMBER:

0	5	0	-	0	2	4	4
---	---	---	---	---	---	---	---

 61 68
EVENT DATE:

1	2	1	6	7	6
---	---	---	---	---	---

 69 74
REPORT DATE:

0	1	0	4	7	7
---	---	---	---	---	---

 75 80

EVENT DESCRIPTION

02 During normal rounds operator noticed liquid coming through insulation on 2" letdown
7 8 9 80
03 diversion line. Upon return to steady state letdown condition, line was isolated.
7 8 9 80
04 (Reportable Occurrence 76-27, 30-day).
7 8 9 80
05
7 8 9 80
06
7 8 9 80

SYSTEM CODE:

C	G
---	---

 7 8 9 10
CAUSE CODE:

B

 11
COMPONENT CODE:

P	I	P	E	X	X
---	---	---	---	---	---

 12 17
PRIME COMPONENT SUPPLIER:

N

 43
COMPONENT MANUFACTURER:

K	0	5	5
---	---	---	---

 44 47
VIOLATION:

N

 48

CAUSE DESCRIPTION

08 A pinhole leak was found in socket weld between pipe and elbow. Weld was built up
7 8 9 80
09 in area of leak, and a visual inspection performed upon return of system to service ver
7 8 9 80
10 ified leak was stopped. This section of line will be (cont'd. under Additional Factors)
7 8 9 80

FACILITY STATUS:

E

 9
% POWER:

1	0	0
---	---	---

 10 12
OTHER STATUS:

NA

 13
METHOD OF DISCOVERY:

b

 44 45
DISCOVERY DESCRIPTION:

Operator making rounds

 46 80
FORM OF ACTIVITY RELEASED:

2

 9
CONTENT OF RELEASE:

2

 10 11
AMOUNT OF ACTIVITY:

NA

 44
LOCATION OF RELEASE:

NA

 45 80

PERSONNEL EXPOSURES

13 NUMBER:

0	0	0
---	---	---

 7 8 9 11
TYPE:

2

 12
DESCRIPTION:

NA

 13 80

PERSONNEL INJURIES

14 NUMBER:

0	0	0
---	---	---

 7 8 9 11
DESCRIPTION:

NA

 12 80

OFFSITE CONSEQUENCES

15

NA

 7 8 9 80

LOSS OR DAMAGE TO FACILITY

16 TYPE:

2

 7 8 9 10
DESCRIPTION:

NA

 11 80

PUBLICITY

17

NA

 7 8 9 80
8304070097 770527
PDR ADOCK 05000244
S PDR

ADDITIONAL FACTORS


18 (cont'd. from Cause Description) replaced at next refueling shutdown to remove weld
7 8 9 80
19 which had been leaking. CAR 1111 was issued to document this corrective action.
7 8 9 80

NAME: James Witte/D. Hamelink

PHONE: 715-546-2700, ext. 291-215



IE FILE COPY



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

January 4, 1977



Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 76-27 (30-day report), Leak in letdown
diversion line
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.9.2b, the attached report of Reportable Occurrence 76-27, 30-day, is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

L. D. White, Jr.
L. D. White, Jr.

Attachment

cc: Dr. Ernst Volgenau (30)
Mr. William G. McDonald (3)