

LER 76-12/3L  
**LICENSEE EVENT REPORT**

CONTROL BLOCK: 

--	--	--	--	--	--

  
1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME: 

01	N	Y	R	E	G	1
----	---	---	---	---	---	---

 14  
7 8 9  
LICENSE NUMBER: 

0	0	-	0	0	0	0	0	-	0	0
---	---	---	---	---	---	---	---	---	---	---

 25  
26  
LICENSE TYPE: 

4	1	1	1	1
---	---	---	---	---

 30  
31 32  
EVENT TYPE: 

0	3
---	---

CON'T: 

01
----

 7 8  
CATEGORY: 

--	--

 57 58  
REPORT TYPE: 

L
---

 59  
REPORT SOURCE: 

L
---

 60  
DOCKET NUMBER: 

0	5	0	-	0	1	4	4
---	---	---	---	---	---	---	---

 61 68  
EVENT DATE: 

0	3	3	1	7	6
---	---	---	---	---	---

 69 74  
REPORT DATE: 

0	4	2	3	7	6
---	---	---	---	---	---

 75 80

**EVENT DESCRIPTION**

02
----

 During routine 60 psig pressure decay test of personnel hatch air lock excessive leakage  
7 8 9 80  

03
----

 was observed from an outer door handwheel shaft packing. Leakage from an air lock  
7 8 9 80  

04
----

 shaft packing was previously reported 3/30/70. The packing nut was threaded back in  
7 8 9 80  

05
----

 packing gland and tightened. The airlock volume was retested satisfactorily with no  
7 8 9 80  

06
----

 adjustment required on the redundant door. (Reportable Occurrence 76-12, 30-day)  
7 8 9 80

SYSTEM CODE: 

Z	Z
---	---

 7 8 9 10  
CAUSE CODE: 

F
---

 11  
COMPONENT CODE: 

Z	Z	Z	Z	Z	Z
---	---	---	---	---	---

 12 17  
PRIME COMPONENT SUPPLIER: 

Z
---

 43  
COMPONENT MANUFACTURER: 

Z	9	9	9
---	---	---	---

 44 47  
VIOLATION: 

N
---

 48

**CAUSE DESCRIPTION**

08
----

 The shaft packing nut backed off due to repeated door operation during concentrated  
7 8 9 80  

09
----

 maintenance efforts during the refueling outage. Action to prevent recurrence is being  
7 8 9 80  

10
----

 investigated.  
7 8 9 80

FACILITY STATUS: 

H
---

 7 8 9  
% POWER: 

0	0	0
---	---	---

 10 12 13  
OTHER STATUS: 

NA
----

 44  
METHOD OF DISCOVERY: 

b
---

 45  
DISCOVERY DESCRIPTION: 

NA
----

 46 80  
FORM OF ACTIVITY RELEASED: 

Z
---

 7 8 9  
CONTENT OF RELEASE: 

Z
---

 10 11  
AMOUNT OF ACTIVITY: 

NA
----

 44  
LOCATION OF RELEASE: 

NA
----

 45 80

**PERSONNEL EXPOSURES**

NUMBER: 

0	0	0
---	---	---

 7 8 9 11  
TYPE: 

Z
---

 12  
DESCRIPTION: 

NA
----

 13 80

**PERSONNEL INJURIES**

NUMBER: 

0	0	0
---	---	---

 7 8 9 11  
DESCRIPTION: 

NA
----

 12 80

**OFFSITE CONSEQUENCES**

15
----

NA
----

  
7 8 9 80

**LOSS OR DAMAGE TO FACILITY**

TYPE: 

Z
---

 7 8 9 10  
DESCRIPTION: 

NA
----

 80

**PUBLICITY**

17
----

NA
----

  
7 8 9 80

**ADDITIONAL FACTORS**

18
----

NA
----


  
7 8 9 80

19
----

--

  
7 8 9 80

NAME: Charles V. Hartlieb PHONE: 716/546-2700, ext. 291-216



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.  
VICE PRESIDENT

TELEPHONE  
AREA CODE 716 546-2700

April 23, 1976

Mr. James P. O'Reilly, Director  
U. S. Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region I  
631 Park Avenue  
King of Prussia, Pennsylvania 19406



Subject: Reportable Occurrence 76-12 (30-day report), Containment  
personnel airlock handwheel shaft seal excessive leakage  
during testing  
R. E. Ginna Nuclear Power Plant, Unit No. 1  
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.9.2b, the attached report of Reportable Occurrence 76-12 (30-day) is hereby submitted. Two additional copies of this letter and the attachment are enclosed.

Very truly yours,

*L. D. White, Jr.*  
L. D. White, Jr.

Attachment

cc: Dr. Ernst Volgenau (30)  
Mr. William G. McDonald (3)

4169