

LICENSEE EVENT REPORT

CONTROL BLOCK

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER								LICENSE TYPE					EVENT TYPE						
[0]	[1]	N	Y	R	E	G	I	[0]	[0]	-	[0]	[0]	[0]	[0]	[0]	-	[0]	[0]	[4]	[1]	[1]	[1]	[1]	[0]	[3]
7	8	9					14	15									25	26					30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE									
[0]	[1] CON'T	[]	[L]	[L]	[0]	[5]	[0]	-	[0]	[2]	[4]	[4]	[0]	[2]	[2]	[8]	[7]	[6]	[0]	[3]	[2]	[2]	[7]	[6]
57	58	59	60		61							68	69					74	75					80

EVENT DESCRIPTION

02	During surveillance test of volume between CV purge supply valves excessive leakage	80
03	was observed from the valve inside CV. Leakage through redundant valve was minimal.	80
04	Valve motion was erratic and valve did not close fully each time. Spring cylinder assem-	80
05	bly piston shaft was smoothed, polished and dry lubricated. Volume was retested satis-	80
06	factorily. Leakage from this and similar valves was reported previously 2/14/74, 11/19/74, 2/6/76 and 2/9/76. (Reportable Occurrence 76-10, 30-day)	80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION			
0	7	S	D	E	V	A	L	V	O	P	N	P	3	4	0	N
7	8	9	10	11	12					17	43	44			47	48

CAUSE DESCRIPTION

08 Excessive friction between the spring cylinder assembly piston shaft and its guide bush-
7 8 9
09 ling resulted from the shaft being heavily scored. The assembly is to be dismantled and
7 8 9
10 inspected with the services of a vendor representative (cont'd. under Additional Factors)
7 8 9

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION		
1	1	H	0	0	0	NA	b		NA		80
7	8	9	10	11	12	13	44	45	46	80	

FORM OF ACTIVITY RELEASED: 1 2 7 8 9 10 11 44
CONTENT OF RELEASE: Z NA
AMOUNT OF ACTIVITY: NA
LOCATION OF RELEASE: NA 45 60

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	2	NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	NA

OFFSITE CONSEQUENCES

15	NA
----	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	2	NA

8 9 10

B204070

PUBLICITY

17 NA S PDR

8304070617 760621
PDR ADOCK 05000244
S PDR

ADDITIONAL FACTORS

18 (cont'd. from Cause Description) during the present shutdown. These are Henry Pratt

19 Co. Model R2-A anvil seat 48" butterfly valves.

NAME: Charles V. Hartlieb

PHONE 716/546-2700, ext. 291-216



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649

LEON D. WHITE, JR.
VICE PRESIDENT

TELEPHONE
AREA CODE 716 548-2700

March 22, 1976



Mr. James P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

Subject: Reportable Occurrence 76-10 (30-day report), Containment purge
supply valve excessive leakage during testing
R. E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. O'Reilly:

In accordance with Technical Specifications, Article 6.9.2b, the attached
report of Reportable Occurrence 76-10, 30-day, is hereby submitted. Two
additional copies of this letter and the attachment are enclosed.

Very truly yours,

L. D. White, Jr.
L. D. White, Jr.

Attachment

cc: Mr. John G. Davis (30)
Mr. William G. McDonald (3)