

WD SIL SPN SVR

WESTERN UNION COMMUNICATIONS

59-237  
Bell  
Jof

1977 AUG 10 04:139  
J.S. ATTY GEN'S OFFICE  
WASHINGTON

USAEC HQS GTWN

WUWEN

TLXA177 (48)DEA161

DE JLA141 IN PDF MORRIS ILL 6 587P CDT

DR P A MORRIS, DIRECTOR

DIVN OF REACTOR LICENSING US ATOMIC ENERGY COMMISSION WASHDC  
28545

THIS IS TO CONFIRM CONVERSATION WITH H. DANCE, REGION THREE  
COMPLIANCE, ON AUG 6, 1971 CONCERNING DRESDEN UNIT 2 (HPCI) TURBINE  
FAILURE TO RE-SET. THE UNIT WAS OPERATING AT 480 MWE WHILE  
ROUTINE HPCI SURVEILLANCE WAS CONDUCTED AT 10PM ON AUG 5 1971  
THE HPCI TURBINE FAILED TO RE-SET DUE TO A CONTROL VALVE LIMIT  
SWITCH WHICH WAS OUT OF ADJUSTMENT. THIS FAILURE WOULD HAVE  
PREVENTED THE TURBINE STOP VALVE FROM OPENING HAD THE SYSTEM  
BEEN REQUIRED & IT THEREFORE REPORTED UNDER DPR-9 TECHNICAL  
SPECIFICATION SECTION 6.6.A. REPAIRS WERE MADE & A SUCCESSFUL  
HPCI RUN WAS COMPLETED BY 3PM ON AUG 6 1971

H K HOYT SUPERINTENDENT DRESDEN NUCLEAR POWER STATION.


6 1971 2 HPCI RPPMWE HPCI 10PM 5 1971 HPCI DPR1 -19 6.6.A

HPCI 3PM 6 1971. (545)

IS/94K/Staff 9/27/71  
R/E  
LK

1115P EDT 6AUG71

USAEC HQS GTWN



FOR  
Page  
P-1000

COPY SENT REGION

THL

8304080130 710810  
PDR ADOCK 05000237  
PDR  
Q

14621

3560