

Initial Telephone
Report Date: 5/30/74

Date of
Occurrence: 5/29/74

Initial Written
Report Date: 5/30/74

Time of
Occurrence: 1900

OYSTER CREEK NUCLEAR GENERATING STATION
FORKED RIVER, NEW JERSEY 08731

Abnormal Occurrence
Report No. 50-219/74/ 34

IDENTIFICATION
OF OCCURRENCE:

Violation of the Technical Specifications, paragraph N/A,
Indications of coolant leakage existing in the area of an
incore flux monitor reactor vessel housing located at core coor-
dinate 28-05.

This event is considered to be an abnormal occurrence as de-
fined in the Technical Specifications, paragraph 1.15E.

CONDITIONS PRIOR
TO OCCURRENCE:

<input type="checkbox"/> Steady State Power	<input type="checkbox"/> Routine Shutdown
<input type="checkbox"/> Hot Standby	<input type="checkbox"/> Operation
<input type="checkbox"/> Cold Shutdown	<input type="checkbox"/> Load Changes During
<input checked="" type="checkbox"/> Refueling Shutdown	<input type="checkbox"/> Routine Power Operation
<input type="checkbox"/> Routine Startup	<input type="checkbox"/> Other (Specify)
<input type="checkbox"/> Operation	

The reactor was in the REFUEL mode during a hydrostatic test
at 850 psig pressure and with coolant temperature approximately
155°F.

DESCRIPTION
OF OCCURRENCE:

On Tuesday, May 28, 1974, during a scheduled reactor vessel
hydrostatic test to inspect the pressure boundary following
refueling maintenance activities, leakage was observed in the
vicinity of an incore flux monitor tube located at the bottom
of the reactor vessel. Further investigation conducted on
Wednesday, May 29, 1974, showed evidence of possible leakage
in the area of an incore flux monitor housing penetration

located in the reactor vessel bottom head. A second hydrostatic test was conducted at a pressure of 850 psig at approximately 7:00 p.m. on May 29, 1974, whereupon, water was observed leaking between the monitor housing and the reactor vessel. The leakage was measured under the conditions of 850 psig with a temperature of 164°F, and calculated to be on the order of approximately 0.02 gallons per hour.

APPARENT CAUSE
OF OCCURRENCE:

<input type="checkbox"/> Design	<input type="checkbox"/> Procedure
<input type="checkbox"/> Manufacture	<input type="checkbox"/> Unusual Service Condition
<input type="checkbox"/> Installation/	<input type="checkbox"/> Inc. Environmental
<input type="checkbox"/> Construction	<input type="checkbox"/> Component Failure
<input type="checkbox"/> Operator	<input type="checkbox"/> Other (Specify)

The cause of this event has yet to be determined.

ANALYSIS OF
OCCURRENCE:

As stated in FDSAR Amendment #37, a postulated failure of the flux monitor tube would result in vessel leakage at a rate which would not cause excessive cladding temperatures and for which core reflooding is possible by engineered safety features. This situation is less severe than the design basis accident. To determine the consequences of a weld failure at a housing for an in-core monitor tube, it is assumed that the weld between the housing and the reactor vessel bottom head fails, allowing the housing and the in-core monitor tube to be ejected from the vessel. The hole provided in the bottom head for the housing has a diameter of two inches; this is the assumed break size. The hole has a break area of .0218 ft². Assuming worst conditions, this results in peak clad temperatures less than 1000°F, as updated in FDSAR Amendment #67. This value is well within acceptable limits of the applicable ECCS criteria.

CORRECTIVE
ACTION:

The nuclear steam supply vendor and the reactor vessel manufacturer have been contacted with regard to this condition. Discussion will ensue as to the proper course of action to be taken to resolve this matter. Recommendations will be forthcoming pending complete review of this event by the Plant Operations Review Committee.

Prepared by:

J. S. Sullivan

Date:

5/30/74



To: James P. O'Reilly
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

From: Jersey Central Power & Light Company
Oyster Creek Nuclear Generating Station, Docket #50-219
Forked River, New Jersey 08731

Subject: Abnormal Occurrence Report No. 50-219/74/34

The following is a preliminary report being submitted
in compliance with the Technical Specifications
paragraph 6.6.2.

Preliminary Approval:

J. T. Carroll, Jr. 5/30/74
J. T. Carroll, Jr. Date

cc: Mr. A. Giambusso

Handwritten: 50-219

4962

COPY SENT REGION 1



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION 1
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

MAY 31 1974

H. D. Thornburg, Chief
Field Support and Enforcement Branch
Directorate of Regulatory Operations, HQ

JERSEY CENTRAL POWER AND LIGHT COMPANY
OYSTER CREEK - BWI
ABNORMAL OCCURRENCE AO 74-34

The subject abnormal occurrence report is forwarded for action.

Based on our review of the licensee's preliminary report, it is recommended that RO Headquarters transfer the lead responsibility to DL for review and evaluation of this penetration failure involving primary coolant leakage at the reactor vessel's bottom head. Additionally, DL should be requested to evaluate potential generic aspects of this problem.

RO:I will continue to provide field follow up and review of any forthcoming corrective measures by the licensee in this matter.

E. J. Brunner
E. J. Brunner, Chief
Reactor Operations Branch

Enclosure
AO 74-34

*5-219
inquiry
duped*

Out of 8304080985

F. J. REGER

To: James P. O'Reilly
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

From: Jersey Central Power & Light Company
Oyster Creek Nuclear Generating Station, Docket #50-219
Forked River, New Jersey 08731

Subject: Abnormal Occurrence Report No. 50-219/74/34

The following is a preliminary report being submitted
in compliance with the Technical Specifications
paragraph 6.6.2.

Preliminary Approval:

J. T. Carroll, Jr. 5/30/74
J. T. Carroll, Jr. Date

cc: Mr. A. Giambusso

dup of 8304020489

OYSTER CREEK NUCLEAR GENERATING STATION
FORKED RIVER, NEW JERSEY 08731

Abnormal Occurrence
Report No. 50-219/74/ 34

IDENTIFICATION
OF OCCURRENCE:

Violation of the Technical Specifications, paragraph N/A,
Indications of coolant leakage existing in the area of an
incore flux monitor reactor vessel housing located at core coor-
dinate 28-05.

CONDITIONS PRIOR
TO OCCURRENCE:

<input type="checkbox"/> Steady State Power	<input type="checkbox"/> Routine Shutdown
<input type="checkbox"/> Hot Standby	<input type="checkbox"/> Operation
<input type="checkbox"/> Cold Shutdown	<input type="checkbox"/> Load Changes During
<input checked="" type="checkbox"/> Refueling Shutdown	<input type="checkbox"/> Routine Power Operation
<input type="checkbox"/> Routine Startup	<input type="checkbox"/> Other (Specify)
<input type="checkbox"/> Operation	

The reactor was in the REFUEL mode during a hydrostatic test
at 850 psig pressure and with coolant temperature approximately
135°F.

DESCRIPTION
OF OCCURRENCE:

On Tuesday, May 28, 1974, during a scheduled reactor vessel
hydrostatic test to inspect the pressure boundary following
refueling maintenance activities, leakage was observed in the
vicinity of an incore flux monitor tube located at the bottom
of the reactor vessel. Further investigation conducted on
Wednesday, May 29, 1974, showed evidence of possible leakage
in the area of an incore flux monitor housing penetration

located in the reactor vessel bottom head. A second hydrostatic test was conducted at a pressure of 850 psig at approximately 7:00 p.m. on May 29, 1974, whereupon, water was observed leaking between the monitor housing and the reactor vessel. The leakage was measured under the conditions of 850 psig with a temperature of 164°F, and calculated to be on the order of approximately 0.02 gallons per hour.

APPARENT CAUSE
OF OCCURRENCE:

<input type="checkbox"/> Design	<input type="checkbox"/> Procedure
<input type="checkbox"/> Manufacture	<input type="checkbox"/> Unusual Service Condition
<input type="checkbox"/> Installation/	<input type="checkbox"/> Inc. Environmental
<input type="checkbox"/> Construction	<input type="checkbox"/> Component Failure
<input type="checkbox"/> Operator	<input type="checkbox"/> Other (Specify)

The cause of this event has yet to be determined.

ANALYSIS OF
OCCURRENCE:

As stated in FDSAR Amendment #57, a postulated failure of the flux monitor tube would result in vessel leakage at a rate which would not cause excessive cladding temperatures and for which core reflooding is possible by engineered safety features. This situation is less severe than the design basis accident. To determine the consequences of a weld failure at a housing for an in-core monitor tube, it is assumed that the weld between the housing and the reactor vessel bottom head fails, allowing the housing and the in-core monitor tube to be ejected from the vessel. The hole provided in the bottom head for the housing has a diameter of two inches; this is the assumed break size. The hole has a break area of .0218 ft². Assuming worst conditions, this results in peak clad temperatures less than 1000°F, as updated in FDSAR Amendment #67. This value is well within acceptable limits of the applicable ECCS criteria.

The nuclear steam supply vendor and the reactor vessel manufacturer have been contacted with regard to this condition. Discussion will ensue as to the proper course of action to be taken to resolve this matter. Recommendations will be forthcoming pending complete review of this event by the Plant Operations Review Committee.

CO
AC

by: John S. Sullivan

Date: 5/30/74

P1

TO: B. H. Grier, RO

FS&EB ACTION CONTROL FORM

A. Action Code FO# 402
Name of Licensee and Facility Jersey Central Power and Light Co. (Oyster/
Docket No. or License No. 50-219
Title Transfer of Responsibility
Origin Region I Date Rec'd 5/31/74

B. FS&EB Branch Coordinator:

Bryan _____ Dreher X H. D. Thornburg _____
Ellis _____ Paulus _____ G. Gower _____

C. Action Requested of:

ADREMP _____ MS&POB _____ EPB _____ RPB _____ ADCO X
OB _____ CB _____ TAB _____ OOE _____ REGION _____

Date Requested 6/6/74 Completion Requested by 7/3/74
Reference Memo - E. J. Brunner to H. D. Thornburg dated 5/31/74
and AO-50-219/74-34

D. Action Requested: Please review above referenced documents and
if agreeable transfer lead responsibility to DL.

E. Date Action Completed _____

Close-out (Date & Method) _____

Comments: If completion date is not consistent with your work
schedule, please let us know.

Harold D. Thornburg
Harold D. Thornburg, Chief
Field Support & Enforcement Branch
Directorate of Regulatory Operations

cc: J. G. Davis