



FLORIDA POWER & LIGHT COMPANY

October 24, 1974

Mr. Angelo Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
Office of Regulation
U. S. Atomic Energy Commission
Washington, D. C. 20545



Dear Mr. Giambusso:

TURKEY POINT UNIT NO. 4
DOCKET NO. 50-251
INSPECTION OF SAFETY RELATED
HYDRAULIC PIPE RESTRAINTS

Inspection of the safety related pipe restraints that are accessible during power operation was completed on October 12, 1974, in accordance with the continuing requirements of the Atomic Energy Commission Directorate of Licensing letter of November 8, 1973. One restraint located on the main steam piping had an indicated hydraulic fluid level that was below the minimum acceptable level. This restraint was replaced with a spare unit. The loss of fluid is believed to be the result of mechanical wear of the piston shaft packing as described in our previous inspection report dated August 26, 1974. The inspection included a total of 15 restraints and all are of the Bergen-Paterson design.

Very truly yours,

Robert E. Uhrig
Robert E. Uhrig
Vice President

REU/HNP/cpc

cc: Mr. Norman C. Moseley
Jack R. Newman, Esquire

*50-251
incident*