

August 30, 1974

Mr. Angelo Giambusso  
Deputy Director for Reactor Projects  
Directorate of Licensing  
Office of Regulation  
U. S. Atomic Energy Commission  
Washington, D. C. 20545

Dear Mr. Giambusso:


TURKEY POINT UNIT NO. 4  
DOCKET NO. 50-251  
INSPECTION OF SAFETY RELATED HYDRAULIC  
PIPE RESTRAINTS

Inspection of the safety related hydraulic pipe restraints inaccessible during reactor operation was completed on August 19, 1974 in accordance with the continuing requirements of the Directorate of Licensing letter dated November 8, 1973. The plant was shut down at this time for repair of the 4A steam generator in which there was primary to secondary leakage.

The inspection showed that all of the restraints were operable. Eleven restraints of the Bergen-Paterson design had indicated fluid levels in the lower half of the allowable range. Fluid was added to these restraints to increase the levels to the recommended values.

The inspection included a total of 50 restraints. Thirty-four of these restraints are of the Bergen-Paterson design and sixteen are of the Power Piping design.

Very truly yours,

  
R. E. Uhrig  
Vice President

REU/DWR/cpc

cc: Mr. Norman C. Moseley  
Jack R. Newman, Esquire



9259

8304110133 741024  
PDR ADOCK 05000251  
G PDR

HE COPY SENT REGION