

To: James P. O'Reilly
Directorate of Regulatory Operations
Region I
631 Park Avenue
King of Prussia, Pennsylvania 19406

From: Jersey Central Power & Light Company
Oyster Creek Nuclear Generating Station Docket #50-219
Forked River, New Jersey 08751

Subject: Abnormal Occurrence Report No. 50-219/74/ 22

The following is a preliminary report being submitted
in compliance with the Technical Specifications
paragraph 6.6.2.

Preliminary Approval:

J. T. Carroll, Jr.
J. T. Carroll, Jr. 3/18/74
Date

cc: Mr. A. Giambusso



8304130335 740318
PDR ADOCK 05000219
S PDR

Handwritten: 50219
2383
COPY SENT REGION *[Signature]*

Initial Telephone

Report Date:

3/15/74

Date of

Occurrence:

3/15/74

Initial Written

Report Date:

3/18/74

Time of

Occurrence:

1550OYSTER CREEK NUCLEAR GENERATING STATION
FORKED RIVER, NEW JERSEY 08731Abnormal Occurrence
Report No. 50-219/74/22IDENTIFICATION
OF OCCURRENCE:

Violation of the Technical Specifications, paragraph 2.3.7,
Low Pressure Main Steam Line Pressure Switch, RE23D, was
found to trip at a pressure less than the minimum required
value of 860 psig.

This event is considered to be an abnormal occurrence as de-
fined in the Technical Specifications, paragraph 1.15A.

CONDITIONS PRIOR
TO OCCURRENCE:

<input checked="" type="checkbox"/> Steady State Power	<input type="checkbox"/> Routine Shutdown
<input type="checkbox"/> Hot Standby	<input type="checkbox"/> Operation
<input type="checkbox"/> Cold Shutdown	<input type="checkbox"/> Load Changes During
<input type="checkbox"/> Refueling Shutdown	<input type="checkbox"/> Routine Power Operation
<input type="checkbox"/> Routine Startup	<input type="checkbox"/> Other (Specify)
<input type="checkbox"/> Operation	

Power: Reactor, 1902 MWt
Elec., 661 MWe
Flow: Recirc., 15.3×10^4 gpm
Feed., 7.10×10^6 lb/hr
Reactor Pressure: 1020 psig
Stack Gas: 40,600 μ Ci/sec

DESCRIPTION
OF OCCURRENCE:

On Friday, March 15, 1974, at 1550, while performing a routine
surveillance test on the four Main Steam Line Low Pressure
Switches, it was discovered that RE23D tripped at 850 psig.
This value is below the minimum required trip point of 860
psig which is derived by adding to the Technical Specification
limit of 850 psig a 10 psig head correction factor.

The "as found" and "as left" switch settings were:

	<u>"As Found" Settings</u>	<u>"As Left" Settings</u>
RE23A	865 psig	861 psig
RE23B	864 psig	864 psig
RE23C	865 psig	865 psig
RE23D	850 psig	860 psig

Pressure switch RE23D was immediately recalibrated and rechecked to actuate at 860 psig.

APPARENT CAUSE
OF OCCURRENCE:

<input checked="" type="checkbox"/> Design	<input type="checkbox"/> Procedure
<input type="checkbox"/> Manufacture	<input type="checkbox"/> Unusual Service Condition
<input type="checkbox"/> Installation/	<input type="checkbox"/> Inc. Environmental
<input type="checkbox"/> Construction	<input type="checkbox"/> Component Failure
<input type="checkbox"/> Operator	<input type="checkbox"/> Other (Specify)

Switch repeatability is a recognized problem and work is in progress to formulate a final solution.

ANALYSIS OF
OCCURRENCE:

As indicated in the bases of the Technical Specifications, "The low pressure isolation of the Main Steam Lines at 850 psig was provided to give protection against fast reactor depressurization and the resultant rapid cooldown of the vessel. Advantage was taken of the scram feature which occurs when the Main Steam Isolation Valves are closed to provide for reactor shutdown so that high power operation at low reactor pressure does not occur, thus providing protection for the fuel cladding integrity safety limit."

The adverse consequences of reactor isolation occurring at reactor pressure approximately 10 psig below the specified minimum value of 860 psig is limited to those effects attendant to

a greater than normal reactor cooldown rate. The fuel cladding integrity safety limit only comes into effect for power operation at reactor pressures less than 600 psig or for power operation greater than 354 MWt with less than 10% recirculation flow. Therefore, the consequences of a 10 psig lower than normal reactor isolation and scram setpoint has no threatening effect whatsoever on the fuel cladding integrity.

The effects of a too rapid cooldown due to the lower isolation pressure are inconsequential since there is less than 2°F difference between the saturation temperature for 860 psig and 850 psig.

CORRECTIVE
ACTION:

Continuing corrective actions being taken at this time are as stated in Abnormal Occurrence Report Nos. 74-9, 74-10, and 74-12, and as restated herein:

1. Investigation is being conducted into the basis for the steam line low pressure setting of 850 psig. Development of a Technical Specification change to lower the setpoint will follow if results of transient analyses indicate this possibility. (See Abnormal Occurrence Report No. 73-30.)
2. Recommendations to possibly reduce or eliminate the sensor setpoint change problem have been received. It was reported that General Electric tests on a pulsating line to simulate plant conditions show that pre-cycled Barksdale switches show improvement but that the switches still do not meet 1% repeatability. General Electric, therefore, recommended an

Ashcroft switch as it is more accurate. The Ashcroft catalog number is 61 S 6080 BN20-06L-1028.

As a result, one switch of each type (pre-cycled Barksdale and Ashcroft) has been purchased for test and evaluation at Oyster Creek. An Ashcroft switch is currently on hand and undergoing evaluation.


FAILURE DATA: Manufacturer, data pertinent to these switches are as follows:

Meletron Corp. (subsidiary of Barksdale)
Los Angeles, California
Pressure Actuated Switch
Model 372
Catalog #372-6SS49A-293
Range 20-1400 psig
Proof Psi. 1750 G

Previous Abnormal Occurrence Reports involving these switches are:

1. Letter to Mr. A. Giambusso from Mr. D. A. Ross, dated December 24, 1973.
2. Abnormal Occurrence Report No. 74-1.
3. Abnormal Occurrence Report No. 74-9.
4. Abnormal Occurrence Report No. 74-10.
5. Abnormal Occurrence Report No. 74-12.

Prepared by:



Date: 3/18/74

OYSTER CREEK NUCLEAR GENERATING STATION
FORKED RIVER, NEW JERSEY 08731

Abnormal Occurrence
Report No. 50-219/74/22

Report Date

March 22, 1974

Occurrence Date

March 15, 1974

Identification of Occurrence

Violation of the Technical Specifications, paragraph 2.3.7, low pressure main steam line pressure switch RE23D was found to trip at a pressure less than the minimum required value of 860 psig. This event is considered to be an abnormal occurrence as defined in the Technical Specifications, paragraph 1.15A.

Conditions Prior to Occurrence

The plant was operating at steady-state power.

The major plant parameters at the time of the event were as follows:

Power:	Reactor, 1902 MWt
	Electric, 661 MWe
Flow:	Recirculation, 15.3×10^4 gpm
	Feedwater, 7.10×10^6 lb/hr
Reactor Pressure:	1020 psig
Stack Gas:	40,600 μ Ci/sec

Description of Occurrence

On Friday, March 15, 1974, at 1550, while performing a routine surveillance test on the four main steam line low pressure switches, it was discovered that RE23D tripped at 850 psig. This value is below the minimum required trip point of 860 psig which is derived by adding to the Technical Specification limit of 850 psig a 10 psig head correction factor.

The "as found" and "as left" switch settings were:

	<u>"As Found" Settings</u>	<u>"As Left" Settings</u>
RE23A	865 psig	861 psig
RE23B	864 psig	864 psig
RE23C	865 psig	865 psig
RE23D	850 psig	860 psig

Diagnose
8/10/30/4/
8/10/30/30/34/

Pressure switch RE23D was immediately recalibrated and rechecked to actuate at 860 psig.

Apparent Cause of Occurrence

Design is considered to be a major factor contributing to this event. Switch repeatability is a recognized problem and work is in progress to formulate a final solution.

Analysis of Occurrence

As indicated in the bases of the Technical Specifications, "The low pressure isolation of the Main Steam Lines at 850 psig was provided to give protection against fast reactor depressurization and the resultant rapid cool-down of the vessel. Advantage was taken of the scram feature which occurs when the main steam isolation valves are closed to provide for reactor shutdown so that high power operation at low reactor pressure does not occur, thus providing protection for the fuel cladding integrity safety limit."

The adverse consequences of reactor isolation occurring at reactor pressure approximately 10 psig below the specified minimum value of 860 psig is limited to those effects attendant to a greater than normal reactor cool-down rate. The fuel cladding integrity safety limit only comes into effect for power operation at reactor pressures less than 600 psig or for power operation greater than 354 MWt with less than 10% recirculation flow. Therefore, the consequences of a 10 psig lower than normal reactor isolation and scram set point has no threatening effect whatsoever on the fuel cladding integrity.

The effects of a too rapid cool-down due to the lower isolation pressure are inconsequential since there is less than 2°F difference between the saturation temperature for 860 psig and 850 psig.

Corrective Action

Continuing corrective actions being taken at this time are as follows:

1. Investigation is being conducted into the basis for the steam line low pressure setting of 850 psig. Development of a Technical Specification change to lower the set point will follow if results of transient analyses indicate this possibility.
2. Recommendations to possibly reduce or eliminate the sensor set point change problem have been received. It was reported that General Electric tests on a pulsating line to simulate plant conditions show that pre-cycled Barksdale switches show improvement but that the switches still do not meet 1% repeatability. General Electric, therefore, recommended an Ashcroft switch as it is more accurate. The Ashcroft catalog number is 61 S 6080 BN20-06L-1028.

As a result, one switch of each type (pre-cycled Barksdale and Ashcroft) has been purchased for test and evaluation at Oyster Creek. An Ashcroft switch is currently on hand and undergoing evaluation.

Failure Data

Manufacturer data pertinent to these switches are as follows:

Meletron Corporation (Subsidiary of Barksdale)
Los Angeles, California
Pressure Actuated Switch
Model 372
Catalog No. 372-6SS49A-293
Range 20-1400 psig
Proof Psi 1750 G

Previous Abnormal Occurrence Reports involving these switches are:

1. Letter to Mr. A. Giambusso from Mr. D. A. Ross dated December 24, 1973.
2. Abnormal Occurrence Report No. 50-219/74/1
3. Abnormal Occurrence Report No. 50-219/74/9
4. Abnormal Occurrence Report No. 50-219/74/10
5. Abnormal Occurrence Report No. 50-219/74/12

1102yf

Jersey Central Power & Light Company



MADISON AVENUE AT PUNCH BOWL ROAD • MORRISTOWN, N. J. 07960 • 201-539-6111

MEMBER OF THE

General



Public Utilities Corporation

March 22, 1974



Mr. A. Giambusso
Deputy Director for Reactor Projects
Directorate of Licensing
United States Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Giambusso:

Subject: Oyster Creek Station
Docket No. 50-219
Abnormal Occurrence Report No. 50-219/74/22

The purpose of this letter is to forward to you the attached Abnormal Occurrence Report in compliance with paragraph 6.6.2.a of the Technical Specifications.

Enclosed are forty copies of this submittal.

Very truly yours,

Donald A. Ross
Manager, Nuclear Generating Stations

cs
Enclosures

cc: Mr. J. P. O'Reilly, Director
Directorate of Regulatory Operations, Region I

Handwritten: 50-219

2606

COPY SENT REGION II