




Commonwealth Edison  
One First National Plaza, Chicago, Illinois  
Address Reply to Post Office Box 767  
Chicago, Illinois 60690

EBS Ltr. #407-75

Dresden Nuclear Power Station  
R. R. #1  
Morris, Illinois 60450  
July 3, 1975

Mr. James G. Keppler, Regional Director  
Directorate of Regulatory Operation-Region III  
U. S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137



SUBJECT: REPORT OF ABNORMAL OCCURRENCE PER SECTION 6.6.A OF THE TECHNICAL SPECIFICATIONS  
UNIT-2 LOCAL LEAK-RATE TEST SUMMARY SUPPLEMENTARY REPORT (1974-75 REFUELING OUTAGE)

- References:
- 1) Regulatory Guide 1.16 Rev. 1 Appendix A
  - 2) Notification of Region III of U. S. Nuclear Regulatory Commission  
Telephone: Mr. Johnson, 1130 hours on May 8, 1975  
Telegram: Mr. Keppler, 1140 hours on May 8, 1975
  - 3) Drawing Number: M-34
  - 4) Letter dated May 9, 1975 from Mr. B. B. Stephenson to Mr. J. G. Keppler

Report Number: 50-237/75-22

Report Date: July 3, 1975

Occurrence Date: May 7, 1975

Facility: Dresden Nuclear Power Station, Morris, Illinois

#### IDENTIFICATION OF OCCURRENCE

During local leak-rate testing for the recent Unit-2 refueling outage, the volume bounded by valves 2-301-98 & 99 exceeded the maximum allowable limits.

(The enclosed appendix gives a complete listing of all penetrations and associated leakages for the outage mentioned above. This appendix is included to supplement B. B. Stephenson's letter dated May 9, 1975 with the results of the leak tests which were still pending at that time. These results have been circled for identification).

#### CONDITIONS PRIOR TO OCCURRENCE

Unit-2 was in the shutdown mode for a refueling outage.

7352

8304130550 750703  
PDR ADOCK 05000237  
S PDR

July 3, 1975

DESCRIPTION OF OCCURRENCE

At 1900 hours on May 7, 1975 the two check valves in the CRD return line (2-301-95 & 98) were leak-rate tested by the pressure decay method at 48 psig to determine the "as-found" leakage. The two check valves were tested independently by using the 301-99 manual valve as a common boundary. The manual valve was assumed to be leak-tight since a water head was present on the reactor side. Check valve 301-98 had a leakage of 66.788 SCFH which exceeded the limit of 29.38 SCFH.

DESIGNATION OF APPARENT CAUSE OF OCCURRENCE (Equipment Failure)

An inspection of 301-98 following the leak-rate testing revealed that the mating surfaces of the disc and seat were dirty. There were no apparent major defects.

ANALYSIS OF OCCURRENCE

Since check valve 301-95 (in series with valve 301-98) had a leakage of 1.247 SCFH, the total leakage through the penetration would have been well within the Technical Specification limit. Had a line break occurred between the two check valves, the high differential pressure created across valve 301-98 would have seated it adequately in comparison to the 48 psig used for leak testing. Plant personnel and the public were not jeopardized by this occurrence.

CORRECTIVE ACTION


The seating surfaces of the valve were cleaned, and the valve was reassembled and returned to service. The volume was satisfactorily leak-rate tested with a leakage of 11.786 SCFH.

FAILURE DATA

Valve 301-98 is a 4" check valve, body type F-S 900, disc type CR-13, manufactured by Henry Vogt.

Earlier in the refueling outage a modification for installing a test connection between valves 301-98 & 99 was completed. Prior to this modification, valve 301-98 could not be leak-rate tested; consequently, there are no previous failures.

Sincerely,

  
B. B. Stephenson  
Superintendent

BBS:GAR:smp  
File/NRC

# APPENDIX

## Dresden Unit-2 Final Local Leak-Rate Test Summary for 1974-75 Refueling Outage

Type of Penetration	Max. Allowable Through Leakage (SCFH)	Actual % of Limit
Primary Isol. Valve	.	57.12
Bellow Seals	178.29 Combined	1.88
Electrical		3.39
MSIV's	11.5 @ valve	86.76 Max
Double Gasketed Seals	58.76 Combined	7.35

### SUPPLEMENTARY NOTE CONCERNING LPCI CONTAINMENT SPRAY VALVE MO-1501-27B (See Reference 4)

Valve MO-1501-27B was found to have excessive disc-to-seat clearance during the "as found" local leak-rate test. The valve was disassembled and the disc and seat were both lapped. After reassembly, the valve again failed the leak test. Further investigation revealed that the torque switch on the Limitorque operator was out of calibration. After recalibration, once again the leak test failed. The valve was disassembled a second time and again was found to have excessive disc-to-seat clearance. The disc was "bottoming out" before seating completely. Repairs consisted of building up and then regrinding the disc to the proper size. Upon reassembly, the leak test yielded a satisfactory leakage of 0.864 SCFH @ 48 PSIG. This leakage is for both valves 1501-27B & 28B combined.

In an effort to determine the total through-leakage for the penetration, 1501-28B was independently leak-rate tested prior to the repair of 1501-27B. The individual leakage was found to be 2.462 SCFH. This test was performed with an 80 PSIG water head present against the upstream side of the 1501-27B valve. Water leaking past 1501-27B reduced the test volume. This reduction in the test volume caused a given leakage to drop the test pressure faster, indicating greater leakage in spite of the water being added to the test volume past 1501-27B. Consequently, the leakage for 1501-28B appeared to be greater than the leakage for 1501-27B & 28B combined.

# LOCAL LEAK RATE TESTS PERFORMED DURING THE UNIT 2 REFUELING OUTAGE OF 1974-75

TYPE OF PENETRATION: Penetration by Air Valve

TEST NUMBER	PENETRATION NUMBER	VOLUME BEING TESTED	INITIAL LEAK RATE SCFH	INITIAL THRU LEAKAGE SCFH	FINAL LEAK RATE SCFH	FINAL THRU LEAKAGE SCFH
5	X-1077	Penetration Check 220-500 to 570	85.13.783	<del>5.835.941</del>	0.320	<del>0.0</del>
6	X-1078	" 220-620 to 570	5935.304	<del>5.835.941</del>	0.000	<del>0.0</del>
7	X-1078	" 220-500 to 570	3237.952	<del>5.835.941</del>	23.018	<del>0.0</del>
8	X-1078	" 220-620 to 570	350.200	<del>5.835.941</del>	6.100	<del>0.0</del>
9	X-1078	" 1601-200 to 300	9.973	<del>4.107</del>	5.503	<del>2.752</del>
10	X-1078	" 1601-200 to 300	0.477	<del>0.249</del>	10.652	<del>6.518</del>
11	X-1078	" 1601-200 to 300	40.710	<del>10.100</del>	4.000	<del>4.000</del>
12	X-1078	" 1601-200 to 300	6.113	<del>3.007</del>	5.226	<del>3.113</del>
13	X-1078	" 1601-200 to 300	0.0	<del>0.0</del>	0.0	<del>0.0</del>
14	X-1078	" 1601-200 to 300	952.101	<del>14.502</del>	14.502	<del>7.514</del>
15	X-1078	" 1601-200 to 300	13.335	<del>14.502</del>	4.858	<del>2.411</del>
16	X-1078	" 1601-200 to 300	537.267	<del>0.0</del>	0.0	<del>0.0</del>
17	X-1078	" 1601-200 to 300	0.0	<del>0.0</del>	0.0	<del>0.0</del>
18	X-1078	" 1601-200 to 300	551.532	<del>5.246.2</del>	0.0	<del>0.0</del>
19	X-1078	" 1601-200 to 300	52.462	<del>4.331.77</del>	0.0	<del>0.0</del>
20	X-1078	" 1601-200 to 300	987.134	<del>5.246.2</del>	0.202	<del>0.0</del>
21	X-1078	" 1601-200 to 300	7128.100	<del>4.331.77</del>	9.783	<del>4.513</del>
22	X-1078	" 1601-200 to 300	8.782	<del>4.331.77</del>	17.518	<del>0.0</del>
23	X-1078	" 1601-200 to 300	17.518	<del>4.331.77</del>	23.200	<del>0.0</del>
24	X-1078	" 1601-200 to 300	1041.707	<del>6.347</del>	12.693	<del>0.0</del>
25	X-1078	" 1601-200 to 300	10.693	<del>10,365.734</del>		<del>53.037</del>

TOTAL THRU LEAKAGE FOR PAGE

Indicates waterhead present on one side of valve







LOCAL LEAK RATE TESTS PERFORMED DURING THE UNIT 2 REFUELING OUTAGE OF 1974-75

TYPE OF PENETRATION: Double Gasketed Leaks

TEST NUMBER	PENETRATION NUMBER	VOLUME BEING TESTED	INITIAL LEAK RATE SCFH	INITIAL THRU LEAKAGE SCFH	FINAL LEAK RATE SCFH	FINAL THRU LEAKAGE SCFH
7	1601-32A	Torus Vase Penetration Filings	16.171	8.096	4.614	2.707
10	1601-32B		146.041	75.281	0.0	0.0
11	1601-32C		19.287	7.644	0.009	0.015
12	1601-32D		48.859	24.110	0.0	0.0
13	1601-32E		0.0	0.0	0.005	0.019
14	1601-32F		0.0	0.0	0.009	0.015
15	1601-32A		1.947	0.015	0.0	0.0
16	1601-32B		26.031	13.016	0.137	0.070
17	1601-32C		243.847	171.925	0.001	0.006
18	1601-32D		121.721	60.851	0.0	0.0
19	1601-32E		40.716	20.358	2.010	1.607
20	1601-32F		52.347	26.175	0.774	0.100
25		Drumhead Head Filings	0.105	0.053	(0.026)	(0.010)
26	X-100	Equip. Ht. 1	0.007	0.004	(0.050)	(0.010)
27	X-306B	Torus Vase Ht. 1 (West)	0.0	0.0	0.0	0.0
28	X-306A	" (East)	0.0	0.0	0.0	0.0
35	X-136F	TIP Tibut Monitor Filings	0.507	0.255	0.507	0.255
36	X-136E	"	0.455	0.228	0.455	0.228
37	X-136J	"	0.034	0.017	0.034	0.017
38	X-136H	"	0.0	0.0	0.0	0.0
39	X-136C	"	0.0	0.0	0.0	0.0
TOTAL THRU LEAKAGE FOR PAGE				359.042		4.230

\*Indicates waterhead present on one side of valve

LOCAL LEAK RATE TESTS PERFORMED DURING THE UNIT 2 REFUELING OUTAGE OF 1974-75

TYPE OF PENETRATION: Double Bottomed Tank (cont)

[illegible]

\*Indicates waterhead present on one side of valve



LOCAL LEAK RATE TESTS PERFORMED DURING THE UNIT 2 REFUELING OUTAGE OF 1974-75

TYPE OF PENETRATION: Electrical

TEST NUMBER	PENETRATION NUMBER	VOLUME BEING TESTED	INITIAL LEAK RATE SCFH	INITIAL THRU LEAKAGE SCFH	FINAL LEAK RATE SCFH	FINAL THRU LEAKAGE SCFH
44	X-20283	Rad Pos Rod	6.017	3.027	6.017	3.027
45	X-202X	Core Vibration Trans	0.0	0.0	0.0	0.0
46	X-2044	Position Monitor Sig	0.0	0.0	0.0	0.0
47	X-202W	Rad Pos Rod	0.331	0.166	0.331	0.166
48	X-202S	Rad Pos Rod	217.834	0.0	0.0	0.0
49	X-2020	LV Power & Control	6.037	3.020	6.037	3.142
50	X-202H	Position Monitor Sig	0.0	0.0	0.0	0.0
51	X-202J	Position Monitor Sig	0.0	0.0	0.0	0.0
52	X-202F	LV Power & Control	1.326	0.663	1.326	0.663
53	X-202D	HV Power	0.0	0.0	0.0	0.0
54	X-202B	HV Power	0.0	0.0	0.0	0.0
55	X-204T	Rad Pos Rod	0.0	0.0	0.0	0.0
56	X-201S	LV Power & Control	11.342	5.671	0.327	0.165
57	X-2042	HV Power	0.0	0.0	0.0	0.0
58	X-204P	HV Power	0.0	0.0	0.0	0.0
59	X-203C	LV Power & Control	12.652	6.326	1.644	0.822
60	X-205E	LV Power & Control	0.0	0.0	0.0	0.0
61	X-201B	LV Power & Control	0.645	0.323	0.645	0.323
75	X-203A	Rad Pos Rod	1.341	0.671	1.341	0.671
76	X-202A	LV Power & Control	7.242	4.621	0.0	0.0
77	X-204E	Position Monitor Sig	0.165	0.083	0.165	0.083
TOTAL THRU LEAKAGE FOR PAGE				24.550		6.041

\*Indicates waterhead present on one side of valve

LOCAL LEAK RATE TESTS PERFORMED DURING THE UNIT 2 REFUELING OUTAGE OF 1974-75

TYPE OF PENETRATION: Bellows Seals

TEST NUMBER	PENETRATION NUMBER	VOLUME BEING TESTED	INITIAL LEAK RATE SCFH	INITIAL THRU LEAKAGE SCFH	FINAL LEAK RATE SCFH	FINAL THRU LEAKAGE SCFH
77	X-105A	Main Steam Line	0.0	0.0	0.0	0.0
	X-105B	"	0.0	0.0	0.0	0.0
	X-105C	"	211.823	0.0	0.0	0.0
	X-105D	"	0.0	0.0	0.0	0.0
	X-106	Main Steam Line Drain	0.0	0.0	0.0	0.0
	X-107A	Primary Feedwater	0.0	0.0	0.0	0.0
	X-107B	"	0.0	0.0	0.0	0.0
	X-108A	Dec. Condenser Supply	0.0	0.0	0.0	0.0
	X-108B	Dec. Condenser Return	0.0	0.0	0.0	0.0
	X-110A	Shut-down Cooling Supply	0.0	0.0	0.0	0.0
	X-110B	"	0.0	0.0	0.0	0.0
	X-113	Charge Supply	0.0	0.0	0.0	0.0
	X-115A	HPCI Supply	0.0	0.0	0.0	0.0
	X-116A	LPCI Discharge	0.0	0.0	0.0	0.0
	X-116B	"	0.0	0.0	0.0	0.0
	X-123	PECCW Inlet	0.0	12.941	0.0	0.0
	X-124	PECCW Outlet	0.0	0.0	0.0	0.0
	X-125	Vent Low Pressure	0.023	0.012	0.023	0.012
	X-126	Vent to Atmosphere	0.0	0.0	0.0	0.0
	X-130	Stbl. Liquid Out	0.0	0.0	0.0	0.0
	X-144	CRD Return	0.884	0.442	0.884	0.442
TOTAL THRU LEAKAGE FOR PAGE				11.425		0.444

\*Indicates waterhead present on one side of valve

Bill Lake (cont)

TEST NUMBER	PENETRATION NUMBER	VOLUME BEING TESTED	INITIAL LEAK RATE SCFH	INITIAL THRU LEAKAGE SCFH	FINAL LEAK RATE SCFH	FINAL THRU LEAKAGE SCFH
79	X-147	Per Head Cooling	0.0	0.0	0.0	0.0
{	X-147A	Core " 2800g V	0.0	0.0	3.465	1.00
	X-147B		0.047	0.022	2.325	1.65
				0.023		2.516

\*Indicates waterhead present on one side of valve

