

ROCHESTER GAS AND ELECTRIC CORPORATION 59 EAST AVENUE, ROCHESTER, N.Y. 14619

TELEPHONE
AREA CODE 516 5-10-2700

Ginna Station
November 12, 1974

Mr. James P. O'Reilly, Director
Directorate of Regulatory Operations
Region I
U.S.A.E.C.
631 Park Avenue
King of Prussia, Pennsylvania 19406



Subject: Abnormal Occurrence 74-18: Failure of one or more components of an engineered safety feature or plant protection system that causes or threatens to cause the feature or system to be incapable of performing its intended function.
Ginna Station
Docket No. 50-244

Dear Mr. O'Reilly:

While conducting PT-23.36, Containment Isolation Valve Leak Rate Testing, Purge Exhaust Valve, on November 11, 1974, an excessive leakage rate was indicated from the containment side purge exhaust valve.

An examination of the valve showed a crimp in the rubber valve seat. Adjusting segments on both sides of the crimp were relaxed, the crimp was smoothed out, and the adjusting segments tightened.

PT-23.36 was run again and results showed that the leakage rate was well below the Technical Specification limit.

Very truly yours,

Charles E. Platt
Superintendent

CEP:kb

cc: Mr. J.F. O'Leary, A.E.C.
Mr. G.J. Sturthout RG&E
Mr. L.D. White Jr. RG&E

8304140125 741112
PDR ADOCK 05000244
S PDR

11671

COPY SENT REGION 1