

Update report
Previous Report Date 12/02/83

• CONTROL BLOCK:

--	--	--	--	--	--	--

 (1)

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M N P I N 1 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100
LICENSE CODE LICENSE NUMBER LICENSE TYPE CAT 50

CON'T

0	1
7	8

REPORT SOURCE

L	6	0	5	0	0	0	2	8	2	7	1	1	0	4	8	3	8	0	4	1	0	8	4	9
60	61									68	69						74	75						80

DOCKET NUMBER

EVENT DATE

REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During power operation, a control room annunciator on No. 22 Diesel Cooling Water
0 3 | Pump was actuated as a result of a false signal in a control cable which showed
0 4 | the engine was running when in fact it was not. The engine running signal blocks
0 5 | all start signals, so the pump was inoperable for a short time. Tech Spec. 3.3.d
0 6 | applies. No effect on public health and safety. Redundant equipment was operable.
0 7 |
0 8 |

SYSTEM CODE W A		CAUSE CODE B		CAUSE SUBCODE B		COMPONENT CODE I N S T R U				COMP. SUBCODE S		VALVE SUBCODE Z	
EVENT YEAR 8 3		SEQUENTIAL REPORT NO. 0 3 0 0		OCCURRENCE CODE 0 3		REPORT TYPE I		REVISION NO. 1					
ACTION TAKEN F		FUTURE ACTION Z		EFFECT ON PLANT Z		SHUTDOWN METHOD Z		HOURS 0 0 0 0		ATTACHMENT SUBMITTED N		NPRD-4 FORM SUB. N	
PRIME COMP. SUPPLIER A		COMPONENT MANUFACTURER D 2 8 3											

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Inadequate installation instructions for the Dynalco Corp. Series DS900 Digital

1 1 | Speed Indicator. Phone contact with the vender provided the information to make

1 2 | a trouble-free installation and this was done on both diesel cooling water pumps.

1 3 |

1 4 |

FACILITY STATUS (28) E (1) 5 (7) 8
 % POWER (29) 1 0 0 (10) 11 12 13 NA (30) OTHER STATUS (44)
 METHOD OF DISCOVERY (31) A (45) 46 Control room annunciation (32) DISCOVERY DESCRIPTION
 ACTIVITY CONTENT (33) Z (7) 8 9 RELEASED OF RELEASE (34) Z (10) 11 12 13 NA (35) AMOUNT OF ACTIVITY (44)
 LOCATION OF RELEASE (36) NA (45) 46
 PERSONNEL EXPOSURES (37) 0 0 0 (7) 8 9 NUMBER (38) Z (11) 12 13 NA (39) DESCRIPTION
 PERSONNEL INJURIES (40) 0 0 0 (7) 8 9 NUMBER (41) NA (11) 12 13 DESCRIPTION
 LOSS OF OR DAMAGE TO FACILITY (42) Z (7) 8 9 TYPE (43) NA (11) 12 13 DESCRIPTION
 PUBLICITY (44) N (7) 8 9 ISSUED (45) NA (11) 12 13 DESCRIPTION
 8405030005 840430
 PDR ADDCK 05000282
 S PDR
 NRC USE ONLY

NAME OF PREPARER A. A. Hunstad

PHONE 612-388-1121

NHC USE ONLY



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500


April 30, 1984

U S Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42

Updated Licensee Event Report
Inoperability of Diesel Cooling Water Pump No. 22

An updated License Event Report for this occurrence is attached.


David Musolf
Manager - Nuclear Support Services

DMM/TMP/bd

c: Regional Administrator-III, NRC
NRR Project Manager, NRC
Resident Inspector, NRC
MPCA
Attn: J W Ferman

Attachment

IE22
11