

TENNESSEE VALLEY AUTHORITY  
CHATTANOOGA, TENNESSEE  
37401



August 30, 1974



50-260

Mr. John F. O'Leary, Director  
Directorate of Licensing  
Office of Regulation  
U.S. Atomic Energy Commission  
Washington, DC 20545

Dear Mr. O'Leary:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 2 -  
DOCKET NO. 50-260 - FACILITY OPERATING LICENSE DPR-52 - ABNORMAL  
OCCURRENCE REPORT BFAO-50-260/749W

The enclosed report is to provide details concerning failure of  
torus-to-drywell vacuum breaker position indicating light circuits and  
is submitted in accordance with Appendix A to Regulatory Guide 1.16,  
Revision 1, October 1973. This event occurred on Browns Ferry Nuclear  
Plant unit 2 on August 20, 1974.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

*EFT*  
E. F. Thomas  
Director of Power Production

Enclosure

CC (Enclosure):

Mr. Norman C. Moseley, Director  
Region II Regulatory Operations Office, USAEC  
230 Peachtree Street, NW., Suite 818  
Atlanta, Georgia 30303

*50260 inquiry*

8305040100 740830  
PDR ADDCK 05000260  
S PDR

9099  
COPY SENT REGION *II*

## ABNORMAL OCCURRENCE REPORT

Report No.: BFAO-50-260/749W  
Report Date: August 30, 1974  
Occurrence Date: August 20, 1974  
Facility: Browns Ferry Nuclear Plant unit 2

### Identification of Occurrence

Failure of torus-to-drywell vacuum breaker position indicating light circuits of valves FCV 64-28G and FCV 64-28L.

### Conditions Prior to Occurrence

The unit was in a cold shutdown condition.

### Description of Occurrence

On August 20, 1974, during routine surveillance testing, it was observed that the valves FCV 64-28G and FCV 64-28L position indicating light did not operate as required.

The FCV 64-28G green check light, which indicates the valve fully closed, did not go out. The FCV 64-28L red light, which indicates the valve within 3° of full closure, would not go off. The green check light of FCV 64-28L was also reported inoperable but operated properly when investigated.

### Designation of Apparent Cause of Occurrence

The cause of failure of the green check light on valve FCV 64-28C was minor corrosive or scale buildup on the operating plunger of the limit switch mounted on the valve. The cause of failure of the red light was an improperly adjusted limit switch on FCV 64-28L valve.

### Analysis of Occurrence

All valves were operable and would have performed their intended function had they been called upon to do so.

### Corrective Action

All limit switch operating plungers on all torus-to-drywell vacuum breakers have been cleaned, lubricated with a light coat of silicone grease, and tested several times. The red light limit switch on FCV 64-28L was properly adjusted. All valves were satisfactorily retested.

### Failure Data

The failure of the unit 2 check light limit switch on FCV 64-28G is similar to a failure experienced in unit 1 and reported in Abnormal Occurrence Report number BFAO-7411W.

BFAO-50-260/749W

Failure Data (Continued)

Check light limit switch: Licon part No. 65-430095

The adjustment failure of the red light on FCV 64-28L is a first-time incident; therefore, no failure data is available.