

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)

Virgil C. Summer Nuclear Station

DOCKET NUMBER (2)

0 5 0 0 0 3 9 5 1 OF 0 1

PAGE (3)

TITLE (4)

Damaged Kaowool Fire Barrier

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)								
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES	DOCKET NUMBER(S)							
0	4	0	9	8	4	8	4	0	2	1	0	5	0	0	0		
THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR 5: (Check one or more of the following) (11)										0	5	0	0	0			
OPERATING MODE (9)		5		20.402(b)		20.408(e)		60.73(a)(2)(iv)		73.71(b)							
POWER LEVEL (10)		0 0 0		20.408(a)(1)(i)		60.36(e)(1)		60.73(a)(2)(v)		73.71(e)							
				20.408(a)(1)(ii)		60.36(e)(3)		60.73(a)(2)(vi)		OTHER (Specify in Abstract below and in Text, NRC Form 366A)							
				20.408(a)(1)(iii)		60.73(a)(2)(i)		60.73(a)(2)(vii)(A)									
				20.408(a)(1)(iv)		60.73(a)(2)(ii)		60.73(a)(2)(vii)(B)									
				20.408(a)(1)(v)		60.73(a)(2)(iii)		60.73(a)(2)(ix)									

LICENSEE CONTACT FOR THIS LER (12)

NAME	TELEPHONE NUMBER
A. R. Koon, Jr. Assoc. Mgr., Regulatory Compliance	8 0 3 3 4 5 - 5 2 0 9

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRC
A	K	P		N					

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	EXPECTED SUBMISSION DATE (15)	MONTH	DAY	YEAR
<input checked="" type="checkbox"/>	XXXXXX			

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On April 9, 1984, Operations Quality Control identified degradation of Kaowool fire wrap on three (3) cable trays and four (4) conduits located in the chase area of the Control Building (412' and 436' elevations). The Licensee immediately verified the operability of the fire suppression system in the affected areas and established a one (1) hour roving fire watch as required by the Technical Specification 3.7.10. Investigation of this event by the Fire Protection Coordinator attributes the cause to aging and to personnel walking on the wrap. The consequences of this event were minimal. Fire suppression in the affected areas includes smoke detectors and preactions sprinklers which were operable. Repair of the degraded wrap has been completed. Station orientation training now includes care and protection of fire barrier material located throughout the plant. The Licensee plans no additional corrective action.

8405140088 840509
PDR ADDCK 05000395
S PDR

SOUTH CAROLINA ELECTRIC & GAS COMPANY

POST OFFICE 764

COLUMBIA, SOUTH CAROLINA 29218

O. W. DIXON, JR.
VICE PRESIDENT
NUCLEAR OPERATIONS

May 9, 1984

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555


SUBJECT: Virgil C. Summer Nuclear Station
Docket No. 50/395
Operating License No. NPF-12
LER 84-021

Dear Sir:

Please find attached Licensee Event Report #84-021 for the Virgil C. Summer Nuclear Station. This Report is submitted pursuant to the requirements of 10 CFR 50.73(a)(2)(1).

Should there be any questions, please call us at your convenience.

Very truly yours,



O. W. Dixon, Jr.

RJB:OWD/dwf
Attachment

cc: V. C. Summer
T. C. Nichols, Jr./O. W. Dixon, Jr.
E. H. Crews, Jr.
E. C. Roberts
W. A. Williams, Jr.
D. A. Nauman
J. P. O'Reilly
Group Managers
O. S. Bradham
C. A. Price
D. A. Lavigne

J. F. Heilman
C. L. Ligon (NSRC)
K. E. Nodland
R. A. Stough
G. Percival
C. W. Hehl
J. B. Knotts, Jr.
INPO Records Center
NPCF
File

1622