

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME: 01 I L D R S 3 LICENSE NUMBER: 00 -00 00 -00 00 LICENSE TYPE: 4 1 1 1 1 EVENT TYPE: 3

CATEGORY: 01 CON'T REPORT TYPE: L REPORT SOURCE: L DOCKET NUMBER: 05 01 -02 49 EVENT DATE: 11 08 76 REPORT DATE: 11 08 76

EVENT DESCRIPTION

02 DURING A ROUTINE OPERATOR INSPECTION, THE THREADED CONNECTION
03 (UNION) BETWEEN THE VALVE AND THE INSTRUMENT PIPING WAS FOUND TO
04 BE LEAKING ON ISOLATION CONDENSER STEAM LINE FLOW SENSOR INSTRUMENT
05 LINE ISOLATION FLOW CHECK VALVE 3-1301-23. ATTEMPTS TO TIGHTEN THE
06 UNION CAUSED THE LEAKAGE TO INCREASE. THE ISOLATION CONDENSER WAS
07 (SEE ATTACHED SHEET)

SYSTEM CODE: S B CAUSE CODE: E COMPONENT CODE: P I P E X X PRIME COMPONENT SUPPLIER: N COMPONENT MANUFACTURER: M 3 0 3 VIOLATION: N

CAUSE DESCRIPTION

08 DURING OUTAGE MAINTENANCE PERFORMED ON VALVE 3-1301-23, THE UNION
09 APPARENTLY BECAME CROSS-THREADED, PROVIDING A LEAKAGE PATH. THE LEAK-
10 AGE BECAME APPARENT FOLLOWING THE 1000-PSI HYDROSTATIC TEST
11 (SEE ATTACHED SHEET)

FACILITY STATUS: C % POWER: 00 5 OTHER STATUS: NA METHOD OF DISCOVERY: B DISCOVERY DESCRIPTION: NA
 FORM OF ACTIVITY RELEASED: Z CONTENT OF RELEASE: Z AMOUNT OF ACTIVITY: NA LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER: 000 TYPE: Z DESCRIPTION: NA

PERSONNEL INJURIES

NUMBER: 000 DESCRIPTION: NA

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE: Z DESCRIPTION: NA

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19

8306100289 761208
 PDR ADOCK 05000249
 S PDR

NAME: TERRANCE E. LANG

PHONE: EXT. 222

EVENT DESCRIPTION (Continued)

immediately isolated from the reactor. The HPCI system had been demonstrated to be operable. This is not a repetitive event. (50-249/1976-33)

CAUSE DESCRIPTION (Continued)

of the reactor vessel. The union was rethreaded and reinstalled, and the isolation condenser was returned to service. No further corrective action was indicated.



Commonwealth Edison

Dresden Nuclear Power Station

R.R. #1

Morris, Illinois 60450


Telephone 815/942-2920

IE FILE COPY

BBS Ltr. #76-865

December 8, 1976

Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Enclosed please find Reportable Occurrence report number 50-249/1976-33.
This report is being submitted to your office in accordance with the Dresden
Nuclear Power Station Technical Specifications, Section 6.6.B.

B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:jo

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

12519