



Commonwealth Edison
Quad-Cities Nuclear Power Station
Post Office Box 216
Cordova, Illinois 61242
Telephone 309/654-2241

FILE COPY

NJK-76-293

August 7, 1976

J. Keppler, Regional Director
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Reference: Quad-Cities Nuclear Power Station
Docket No. 50-254, DPR-29, Unit 1
Appendix A, Sections 6.6.B.2.c.

Enclosed please find Reportable Occurrence Report No. 50-254/76-21 for Quad-Cities Nuclear Power Station.

This report is submitted to you in accordance with the requirements of Technical Specification 6.6.B.2.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
Station Superintendent

NJK/GS/vmb

cc: G. A. Abrell

COPY SENT REGION III

8306100306 760929
PDR ADDCK 05000254
S PDR

8391

AUG 9 1976

LICENSEE EVENT REPORT

CONTROL BLOCK: _____

1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME				LICENSE NUMBER								LICENSE TYPE				EVENT TYPE								
01	1	L	Q	A	D	1	0	0	-	0	0	0	0	-	0	0	4	1	0	0	0	0	3	
7	8	9				14	15									25	26					30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER				EVENT DATE				REPORT DATE											
01	CON'T		L	0	5	0	-	0	2	5	4	0	7	0	9	7	6	0	8	0	7	7	6
7	8	57	58	59	60	61					68	69				74	75						80

EVENT DESCRIPTION

02	With Unit One shutdown in the REFUEL mode, control rod drive replacement was	80
03	scheduled for five rods. The drive replacement was to be performed on the five rods	80
04	consecutively and not simultaneously on any two rods. Because established procedures	80
05	were not adhered to, two rods were withdrawn simultaneously. Shutdown margin was	80
06	maintained during this occurrence. (R0 50-254/76-21)	80

7 8 9

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER			VIOLATION	
0	7	Z	Z	Z	Z	Z	Z	Z	Z	9	9	9	N
7	8	9	10					43	44			47	48

CAUSE DESCRIPTION

08	Operating personnel did not follow established procedures. When this condition was	80
09	discovered, all rods were inserted to 00. Procedural changes were initiated to	80
10	prevent recurrence.	80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	G	0	0	0	NA	A	NA			
7	8	9	10	11	12	13	44	45	46	80

FORM OF ACTIVITY RELEASED: 12
CONTENT OF RELEASE: 2
AMOUNT OF ACTIVITY: NA
LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	0	NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	NA

OFFSITE CONSEQUENCES

15 | NA | 80

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	Z	NA

PUBLICITY

1	7	NA	80
7	8		

ADDITIONAL FACTORS

18 The second of the two rods withdrawn was done so with the mode switch in STARTUP.

19 The status of the plant was such that a unit startup could have commenced.

NAME: Gary Spedl

PHONE: 309-654-2241 (ext. 242)