

LICENSEE EVENT REPORT

CONTROL BLOCK: ☐ ☐ ☐ ☐ ☐ ☐

PLEASE PRINT ALL REQUIRED INFORMATION

| | | | | | | | | | | | | | | | | | | | | | |
|----------------------------|--|------|--|----------|--|--------------------------------|--|---------------|--|---------------|--|-----------------------|--|------------|--|------------------|--|-------------|--|--|--|
| LICENSEE NAME 01 ILDRS3 | | | | | | LICENSE NUMBER 00-000000-00 | | | | | | LICENSE TYPE 41111 | | | | EVENT TYPE 03 | | | | | |
| 7 | | 8 | | 9 | | 14 | | 15 | | 25 | | 26 | | 30 | | 31 32 | | | | | |
| 01 | | CONT | | CATEGORY | | REPORT TYPE | | REPORT SOURCE | | DOCKET NUMBER | | | | EVENT DATE | | | | REPORT DATE | | | |
| 7 | | 8 | | 57 58 | | 59 | | 60 | | 61 68 69 | | | | 74 | | | | 75 80 | | | |
| 01 | | CONT | | | | L | | L | | 050-0249 | | | | 092476 | | | | 101976 | | | |

EVENT DESCRIPTION

| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|--|---|--|---|--|----|--|---|--|--|--|--|--|--|--|--|--|--|--|----|--|--|--|--|--|----|--|
| 02 | | DURING A ROUTINE INSPECTION OF THE DRYWELL SNUBBERS, SNUBBERS | | | | | | | | | | | | | | | | | | 80 | | | | | | | |
| 7 | | 8 | | 9 | | 03 | | #24 AND #30 APPEARED TO BE IN AN INOPERABLE CONDITION DUE TO LOSS | | | | | | | | | | | | | | | | | | 80 | |
| 7 | | 8 | | 9 | | 04 | | OF FLUID. BOTH SNUBBERS WERE REMOVED AND BENCH-TESTED TO DETER- | | | | | | | | | | | | | | | | | | 80 | |
| 7 | | 8 | | 9 | | 05 | | MINE THE CAUSE OF FAILURE. PREVIOUS FAILURES OF HYDRAULIC | | | | | | | | | | | | | | | | | | 80 | |
| 7 | | 8 | | 9 | | 06 | | PIPING RESTRAINTS HAVE BEEN REPORTED. (50-249/1976-21) | | | | | | | | | | | | | | | | | | 80 | |

| | | | | | | | | | | | | | | | |
|-------------|--|------------|--|----------------|--|--|--|--------------------------|--|------------------------|--|--|--|-----------|--|
| SYSTEM CODE | | CAUSE CODE | | COMPONENT CODE | | | | PRIME COMPONENT SUPPLIER | | COMPONENT MANUFACTURER | | | | VIOLATION | |
| 07 SF | | 08 E | | 09 HANGER | | | | 10 N | | 11 B210 | | | | 12 N | |
| 7 8 9 10 | | 11 | | 12 17 | | | | 43 | | 44 47 | | | | 48 | |

CAUSE DESCRIPTION

| | | | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|--|---|--|---|--|----|--|---|--|--|--|--|--|--|--|--|--|--|--|----|--|--|--|--|--|----|--|
| 08 | | BENCH-TESTING OF THE TWO SNUBBERS REVEALED THAT, DESPITE SOME | | | | | | | | | | | | | | | | | | 80 | | | | | | | |
| 7 | | 8 | | 9 | | 09 | | FLUID LEAKAGE THROUGH THE GREASE FITTINGS, BOTH SNUBBERS DID IN | | | | | | | | | | | | | | | | | | 80 | |
| 7 | | 8 | | 9 | | 10 | | FACT OPERATE PROPERLY. SINCE THE SNUBBERS WOULD HAVE FUNCTIONED | | | | | | | | | | | | | | | | | | 80 | |

| | | | | | | | | | | | | | |
|---------------------------|--|--------------------|--|--------------------|--|--|--|---------------------|--|-----------------------|--|--|--|
| FACILITY STATUS | | % POWER | | OTHER STATUS | | | | METHOD OF DISCOVERY | | DISCOVERY DESCRIPTION | | | |
| 11 H | | 12 000 | | 13 NA | | | | 14 B | | 15 NA | | | |
| 7 8 9 | | 10 | | 12 13 | | | | 44 45 | | 46 80 | | | |
| FORM OF ACTIVITY RELEASED | | CONTENT OF RELEASE | | AMOUNT OF ACTIVITY | | | | LOCATION OF RELEASE | | | | | |
| 12 Z | | 13 Z | | 14 NA | | | | 15 NA | | | | | |
| 7 8 9 | | 10 11 | | 44 45 | | | | 80 | | | | | |

PERSONNEL EXPOSURES

| | | | | | | | |
|--------|--|-------|--|-------------|--|--|--|
| NUMBER | | TYPE | | DESCRIPTION | | | |
| 13 000 | | 14 Z | | 15 NA | | | |
| 7 8 9 | | 11 12 | | 13 80 | | | |

PERSONNEL INJURIES

| | | | | | |
|--------|--|-------------|--|--|--|
| NUMBER | | DESCRIPTION | | | |
| 14 000 | | 15 NA | | | |
| 7 8 9 | | 11 12 80 | | | |

OFFSITE CONSEQUENCES

| | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|--|----|--|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|----|--|--|--|--|--|
| 15 | | NA | | | | | | | | | | | | | | | | | | 80 | | | | | |
| 7 | | 8 | | 9 | | | | | | | | | | | | | | | | | | | | | |

LOSS OR DAMAGE TO FACILITY

| | | | | | |
|-------|--|-------------|--|--|--|
| TYPE | | DESCRIPTION | | | |
| 16 Z | | 17 NA | | | |
| 7 8 9 | | 10 80 | | | |

PUBLICITY

| | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|--|----|--|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|----|--|--|--|--|--|
| 17 | | NA | | | | | | | | | | | | | | | | | | 80 | | | | | |
| 7 | | 8 | | 9 | | | | | | | | | | | | | | | | | | | | | |

ADDITIONAL FACTORS

| | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|--|----|--|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|----|--|--|--|--|--|
| 18 | | NA | | | | | | | | | | | | | | | | | | 80 | | | | | |
| 7 | | 8 | | 9 | | | | | | | | | | | | | | | | | | | | | |

| | | | | | | | | | | | | | | | | | | | | | | | | | |
|----|--|---|--|---|--|--|--|--|--|--|--|--|--|--|--|--|--|--|--|----|--|--|--|--|--|
| 19 | | | | | | | | | | | | | | | | | | | | 80 | | | | | |
| 7 | | 8 | | 9 | | | | | | | | | | | | | | | | | | | | | |

NAME: STEVEN W. HARRIS

PHONE: EXT. 265

CAUSE DESCRIPTION (Continued)

satisfactorily upon demand, the safety implications of this event were minimal.

As corrective action, the leaking grease fittings were replaced, and the snubbers were reinstalled and refilled to the proper operating level. To ensure timely identification of any recurring problem, the inspection interval for these snubbers has been decreased from 1 year to 6 months. Snubbers #24 and #30 are Bergen-Paterson hydraulic shock suppression devices.



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

FILE COPY


BBS Ltr. #76-742

October 19, 1976



Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Enclosed please find Reportable Occurrence report number 50-249/1976-21.
This report is being submitted to your office in accordance with the Dresden
Nuclear Power Station Technical Specifications, Section 6.6.B.


B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:jo

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

10870