

EVENT DESCRIPTION (Continued)

drywell, any leakage would have been contained within the primary containment. This is the first reported leak-rate test failure for these valves. (50-249/1976-20)

CAUSE DESCRIPTION (Continued)

valve body and bonnet. An update report will be submitted after repairs and retesting have been completed. Valve 3-220-1 is a 2-inch globe valve, model 7852-U, manufactured by the Crane Company.



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

IE FILE COPY


BBS Ltr. #76-750

October 22, 1976



Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Enclosed please find Reportable Occurrence report number 50-249/1976-20.
This report is being submitted to your office in accordance with the Dresden
Nuclear Power Station Technical Specifications, Section 6.6.B.


B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:jo

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

10891