

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

<p>LICENSEE NAME</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 01 I L D R S 3 </div> <p style="font-size: small;">7 8 9 14 15</p>	<p>LICENSE NUMBER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 00-000000-00 </div> <p style="font-size: small;">25 26 30 31 32</p>	<p>LICENSE TYPE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 41111 </div> <p style="font-size: small;">30 31 32</p>	<p>EVENT TYPE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 03 </div> <p style="font-size: small;">31 32</p>
<p>CATEGORY</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 01 CONT </div> <p style="font-size: small;">7 8</p>	<p>REPORT TYPE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> L </div> <p style="font-size: small;">57 58</p>	<p>REPORT SOURCE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> L </div> <p style="font-size: small;">59 60</p>	<p>DOCKET NUMBER</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 050-0249 </div> <p style="font-size: small;">61 68</p>
<p>EVENT DATE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 091276 </div> <p style="font-size: small;">69 74</p>		<p>REPORT DATE</p> <div style="border: 1px solid black; padding: 2px; display: flex; justify-content: space-between;"> 101276 </div> <p style="font-size: small;">75 80</p>	

EVENT DESCRIPTION

02 DURING A ROUTINE PLANT INSPECTION, A STEAM LEAK WAS FOUND IN AN

03 ELBOW ON THE "B" MOISTURE SEPARATOR DRAIN TANK LINE TO THE "D" FEED-

04 WATER HEATERS. THE UNIT WAS PLACED IN "STANDBY" AND A TEMPORARY RE-

05 PAIR WAS INITIATED. ALL LEAKAGE WAS CONTAINED IN THE PLANT DRAIN SYSTEM.

06 THEREBY PRECLUDING ANY UNCONTROLLED RELEASE. THIS IS NOT A REPETITIVE EVENT.

(50-249/1976-15)

SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07 H H	E	P I P E X X	A	Z 9 9 9	N
7 8 9 10	11	12 17	43	44 47	48

CAUSE DESCRIPTION

08 A SURGE IN THE PROCESS STREAM RESULTED IN THE FAILURE OF A SUPPORT BOLT ON

09 A RIGID LINE HANGER. THE RESULTANT ADDITIONAL FORCE ON A DOWNSTREAM SUP-

10 PORT, WHICH WAS WELDED TO THE PROCESS LINE, CAUSED A CRACK TO DEVELOP IN

(SEE ATTACHED SHEET)

FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11 E	075	NA	B	NA
7 8 9	10 12 13	44	45 46	80

FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12 Z	Z	NA	NA
7 8 9	10 11	44	45 80

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION
13 000	Z	NA
7 8 9 11	12	13 80

PERSONNEL INJURIES

NUMBER	DESCRIPTION
14 000	NA
7 8 9 11	12 80

OFFSITE CONSEQUENCES

NUMBER	DESCRIPTION
15	NA
7 8 9	80

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION
16 Z	NA
7 8 9 10	80

PUBLICITY

NUMBER	DESCRIPTION
17	NA
7 8 9	80

ADDITIONAL FACTORS

NUMBER	DESCRIPTION
18	NA
7 8 9	80

NUMBER	DESCRIPTION
19	
7 8 9	80

8306100358 761012
PDR ADOCK 05000249
S PDR

NAME: C.E. SARGENT

PHONE: EXT. 265

CAUSE DESCRIPTION (Continued)

the process pipe in the area of the attachment weld. The crack was ground and covered with weld material as a temporary repair. The affected area was permanently repaired during the current refueling outage.

This section of piping has occasionally experienced system surges and oscillations. Additional restraints were already scheduled for installation before the failure occurred. Installation of these additional shock suppression devices should preclude a recurrence of this nature.




Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

BBS Ltr. #76-724

October 12, 1976

Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Enclosed please find Reportable Occurrence report number 50-249/1976-15.
This report is being submitted to your office in accordance with the Dresden
Nuclear Power Station Technical Specifications, Section 6.6.B.



B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:jo

Enclosure

cc: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC



10519

COPY SENT REGION 