



Commonwealth Edison
Quad-Cities Generating Station
Post Office Box 216
Cordova, Illinois 61242
Telephone 309/654-2241

NJK-76-241

July 1, 1976

J. Keppler, Regional Director
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station
Docket No. 50-254, DPR-29, Unit 1
Appendix A, Sections 3.5.C, 6.6.B.1.e




Enclosed please find Reportable Occurrence Report No. 50-254/76-19 for Quad-Cities Nuclear Power Station.

This report is submitted to you in accordance with the requirements of Technical Specification 6.6.B.1.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION


N. J. Kalivianakis
Station Superintendent

NJK/1k

cc: G. A. Abrell

8306130020 760701
PDR ADOCK 05000254
S PDR

7301

~~COPY SENT REGION~~

JUL 6

CENSEE EVENT REPORT

CONTROL BLOCK:

1						6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME						LICENSE NUMBER								LICENSE TYPE					EVENT TYPE				
01	1	L	Q	A	D	1	0	0	-	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9				14	15									25	26					31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER							EVENT DATE					REPORT DATE							
01	CON'T	T	L	0	5	0	-	0	2	5	4	0	6	1	7	7	6	0	7	0	1	7	6
7	8	57	58	59	60	61					68	69					74	75					80

EVENT DESCRIPTION

Event Number	Event Description	Page
02	HPCI Motor Speed Changer (MSC) failed to operate during monthly surveillance. The	80
03	MSC would not move off the low speed stop because its linkage was bound. HPCI	80
04	operation was immediately restored by turning the MSC handwheel to free the linkage.	80
05	Subsequent inspection revealed no mechanical abnormality or excessive wear.	80
06	Lubrication resolved the problem as demonstrated by cycling the MSC satisfactorily.	80

7 8 9

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION		
0	7	S F	E	T	U	R	B	I	N	N	G	O	8	O	N
7	8	9	10	11	12				17	43	44			47	48

CAUSE DESCRIPTION

08	Proximate Cause-Component Failure. The HPCI MSC bound due to inadequate lubrication.	80
09	To prevent recurrence, a lubrication schedule has been established for both units.	80
10	This is the first occurrence of this type at Quad-Cities Station.	80

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	0	3	7	NA	B	NA			
7	8	9	10	11	12	13	44	45	46	80
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY			LOCATION OF RELEASE			
12	Z	Z	NA				NA			
7	8	9	10	11	12	13	44	45	46	80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
13	0	0	0	Z	NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	NA

OFFSITE CONSEQUENCES

1	5	NA
7	8	9

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16	Z	NA

PUBLICITY

17	NA
----	----

ADDITIONAL FACTORS

1	8	EVENT DESCRIPTION (CONT) (RO 50-254/76-19).
---	---	---

19

7 8 9

80

NAME: J. Vahrenwald

PHONE: 309-654-2241 ext. 248