



Commonwealth Edison
Quad Cities Nuclear Power Station
22710 206 Avenue North
Cordova, Illinois 61242
Telephone 309/654-2241

D. J. LAYMAN
LE FILE COPY

NJK-77-9

January 6, 1977



J. Keppler, Regional Director
Office of Inspection and Enforcement
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station
Docket No. 50-265, DPR-30, Unit 2
Appendix A, Sections 3.1.A and 6.6.B.2.a, Table 3.1-3

Enclosed please find Reportable Occurrence Report No. RO 50-265/76-18 for Quad-Cities Nuclear Power Station. This event had initially been designated as a Non-Reportable Occurrence on November 14, 1976 and the investigation report was completed on December 13, 1976. However, subsequent review and analysis of this occurrence have revealed that the event was reportable as required by Technical Specification 6.6.B.2.a.

Very truly yours,

COMMONWEALTH EDISON COMPANY
QUAD-CITIES NUCLEAR POWER STATION

N. J. Kalivianakis
N. J. Kalivianakis
Station Superintendent

NJK/LFG/lk

cc: G. A. Abrell

584

8306130026 770106
PDR ADOCK 05000265
S PDR

JAN 12 1977

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 2 3 4 5 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	1	L	Q	A	D	2	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3		
7	8	9				14	15											25	26				30	31	32	

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER					EVENT DATE					REPORT DATE									
01	CONT	L	L	0	5	0	-	0	2	6	5	1	1	1	4	7	6	0	1	0	6	7	7
7	8	57	58	59	60	61				68	69							74	75				80

EVENT DESCRIPTION

02	While performing the Reactor Protection System (RPS) Channel B Main Steam Isolation																							80
03	Valve (MSIV) monthly Scram Sensor Functional Test, a half-scam signal was not																							80
04	received for MSIV A0-2-203-1D. Also, a MSIV not fully open alarm did not annunciate																							80
05	on control room panel 902-5. The immediate corrective action was to remove fuse																							80
06	590-702H to de-energize relay 590-102H in RPS Channel B, thereby placing the																							80

SYSTEM CODE		CAUSE CODE		COMPONENT CODE					PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER					VIOLATION	
07	1	A	E	C	K	T	B	R	K	L	N	0	1	5	N		
7	8	9	10	11	12					17	43	44			47	48	

CAUSE DESCRIPTION

08	(Proximate Cause-Component Failure) One of the RPS limit switches on A0-2-203-1D,																							80
09	which is connected to relay 590-102H, failed due to the harsh environment inside the																							80
10	drywell created by high temperatures in the vicinity of the Main Steam Lines.																							80

FACILITY STATUS		% POWER		OTHER STATUS					METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
11	F	0	3	8	NA					B	Monthly MSIV Scram Functional Test					
7	8	9	10	12	13					44	45	46				80

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY					LOCATION OF RELEASE				
12	Z	Z	NA					NA					
7	8	9	10	11					44	45			80

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION					
13	0	0	0	Z	NA				
7	8	9	11	12	13				80

PERSONNEL INJURIES

NUMBER		DESCRIPTION						
14	0	0	0	NA				
7	8	9	11	12				80

OFFSITE CONSEQUENCES

15	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION					
16	3	NA					
7	8	9	10				80

PUBLICITY

17	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

ADDITIONAL FACTORS

18	(Event Description continued) instrument channel in the tripped condition. The																							80
19	590-102G relay to RPS Channel A was then tested and found to be operable. (cont)																							80

NAME: James Swales PHONE: 309-654-2241 Ext. 248

EVENT DESCRIPTION CONTINUED

During this occurrence, the scram relays on Channel B were functional; only the limit switch connected to relay 590-102H had failed. All other MSIV's performed satisfactorily during the test, and would have performed as required had an MSIV closure condition presented itself. The 590-102G relay was functional; therefore, the 1D MSIV would have initiated a half-scram on Channel A upon 10% closure.

Corrective Action to Prevent Recurrence

The immediate corrective action taken assured that the 1D MSIV would initiate a half-scram on RPS Channel B. The limit switch was replaced during a Unit Two weekend outage from December 2 to December 6, 1976. Subsequent Scram Functional Testing was successful.

Failure Data

There have been many instances of MSIV limit switch failure in the past. Most of these failures have attributed to the harsh environment in the area of the MSIV's. The original limit switches on all MSIV's in the Unit One and Unit Two Drywells have been replaced with hermetically sealed limit switches. This corrective action has greatly reduced the frequency of occurrences of this type. The outboard MSIV's of Unit Two have these new switches, and those on Unit One will be replaced during the upcoming refueling outage. Investigations are in progress to determine a further solution to the limit switch failure problem. A possible remedy may be moving the limit switches out of the direct line of any MSIV stem leaks, to thus provide a better location for the switches. The limit switches are manufactured by NAMCO, type SL-3CT.