

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME										LICENSE NUMBER										LICENSE TYPE					EVENT TYPE	
01	I	L	D	R	S	3	0	0	-	0	0	0	0	-	0	0	4	1	1	1	1	0	3			
7	8	9	14	15	25	26	30	31	32																	
CATEGORY		REPORT TYPE		REPORT SOURCE		DOCKET NUMBER					EVENT DATE					REPORT DATE										
01	CON'T			L	L	0	5	0	-	0	2	4	9	0	4	3	0	7	6	0	5	2	8	7	6	
7	8	57	58	59	60	61	68	69	74	75	80															

EVENT DESCRIPTION

02	DURING SURVEILLANCE TESTING, THE CCSW PUMP VAULT PENETRATIONS WERE FOUND																							80
03	TO LEAK WHEN PRESSURIZED AS REQUIRED BY THE TECH SPECS. WORK REQUEST # 3708 WAS																							80
04	INITIATED FOR RESEALING THE NINE PENETRATIONS. UPON COMPLETION OF REPAIRS, THE																							80
05	PENETRATIONS WERE RETESTED AND EXHIBITED ZERO LEAKAGE. A SIMILAR EVENT OCCURRED																							80
06	ON UNIT-2 CCSW VAULT PENETRATIONS, WHICH PROMPTED TESTING OF THE CORRE-																							80
(CONTINUED BELOW)																								

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER				VIOLATION	
07	S	F	B	P	E	N	E	T	A	Z	9	9	9	Y	
7	8	9	10	11	12	17	43	44	47	48					

CAUSE DESCRIPTION

08	FAILURE OF THE PENETRATION SEALS WAS ATTRIBUTED TO IMPROPER APPLICATION																							80
09	OF THE SILICONE SEALANT (RTV) AND TO OPERATIONAL VIBRATION.																							80
10																								80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION					
11	H	0	0	0	NA	C	NA						
7	8	9	10	12	13	44	45	46	80				
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE					
12	Z	Z	NA				NA						
7	8	9	10	11	44	45	80						

PERSONNEL EXPOSURES

NUMBER		TYPE		DESCRIPTION	
13	0	0	0	Z	NA
7	8	9	11	12	13

PERSONNEL INJURIES

NUMBER		DESCRIPTION	
14	0	0	NA
7	8	9	12

OFFSITE CONSEQUENCES

15	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION																					
16	Z	NA																					
7	8	9	10	80																			

PUBLICITY

17	NA																							80
----	----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

8306130042 760528
PDR ADOCK 05000249
S PDR

ADDITIONAL FACTORS EVENT DESCRIPTION (CONT.)

18	SPONDING PENETRATIONS ON UNIT-3. (50-249/1976-8)																							80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

19																								80
----	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	--	----

NAME: STEVEN W. HARRIS

PHONE: EXT. 265



Commonwealth Edison
Dresden Nuclear Power Station
R.R. #1
Morris, Illinois 60450
Telephone 815/942-2920

BBS Ltr. #413-76

May 27, 1976



Mr. James G. Keppler, Regional Director
Directorate of Regulatory Operations - Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Enclosed please find Reportable Occurrence number 50-249/1976-8.
This report is being submitted to your office in accordance with the
Dresden Nuclear Power Station Technical Specifications, Section 6.6.B.

Arthur M. Roberts
for B. B. Stephenson
Station Superintendent
Dresden Nuclear Power Station

BBS:smp

Enclosure

CC: Director of Inspection & Enforcement
Director of Management Information & Program Control
File/NRC

COPY SENT REGION III

5606