



Commonwealth Edison  
Quad-Cities Nuclear Power Station  
Post Office Box 216  
Cordova, Illinois 61242  
Telephone 309/654-2241

NJK-75-429

Telecopy: Region III, Attention: Mr. C. Feierabend

August 25, 1975

J. Keppler, Regional Director  
Office of Inspection and Enforcement  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Reference: Quad-Cities Nuclear Power Station, Unit 2  
Docket No. 50-265, DPR-30  
Appendix A, Sections 1.0.A.2, 3.6.1.1, 6.6.B.1.a

Dear Mr. Keppler:


The purpose of this letter is to provide you with notification of an Abnormal Occurrence as required by Technical Specification 6.6.B.1.a within 24 hours of the occurrence.

On August 24, 1975, during an inspection of hydraulic snubbers, one Grinnell snubber on the main steam drain line and one Bergen-Patterson snubber on the reactor recirculation system were found faulty. The Grinnell snubber had an empty fluid reservoir and the Bergen-Patterson snubber had a leaking accumulator. Work requests were issued for repair of the snubbers; replacement parts were installed prior to the reactor startup on August 25, 1975.

This occurrence was discussed by telephone with Mr. Feierabend of your office on August 25, 1975. Further information will be provided by Abnormal Occurrence Report AO 50-265/75-32 which will be submitted within 10 days of the date of this occurrence.

Very truly yours,

COMMONWEALTH EDISON COMPANY  
QUAD-CITIES NUCLEAR POWER STATION

  
N.J. Kalivianakis  
Station Superintendent

NJK/SRH/vmb

cc: Office of Nuclear Reactor Regulation  
G.A. Abrell

8306160152 750903  
PDR ADOCK 05000265  
S PDR



Commonwealth Edison

## DEVIATION REPORT

DVR NO.  
STA UNIT YEAR NO.  
D-4-2-75-84

## PART 1 TITLE OF EVENT

OCCURRED

8/24/75 2:00

DATE

TIME

SYSTEM AFFECTED

PLANT CONDITIONS

TESTING

☐ YES ☒ NO

DESCRIPTION OF EVENT

While performing routine inspection of hydraulic snubbers  
Grinnel snubber number 9751 was found to have  
an empty oil reservoir. Also Bergen-Patterson snubber mark no. 146  
was found to have a leaky accumulator,  
suspected leaky seals or fittings

DESCRIPTION OF INITIAL ACTION

Reported findings to maintenance.

EQUIPMENT ☒ YES  
FAILURE ☐ NO

DR NO.

WB NO.  
3282-75  
3261-75

COMPLETED

T. P. Joyce

RESPONSIBLE SUPERVISOR

8/22/75

DATE

## PART 2 DESCRIPTION OF SAFETY IMPLICATIONS, ACTIONS TO PREVENT RECURRENCE, AND ACTIONS TO PREVENT OCCURRENCE ON SIMILAR COMPONENTS OR SYSTEMS.

Safety implications are minimal since the probability of having  
an occurrence that would require the snubbers to be  
operable are small.

6-MONTH  
REPORT☒ YES  
☐ NO30-DAY  
REPORT☐ YES  
☒ NOINCIDENT  
(10-DAY)  
REPORT☒ YES  
☐ NO

INCIDENT NO.

STA UNIT YEAR NO.  
I-4-2-75-32

ACTION ITEM NO.

REVIEWED AND COMPLETED

J. J. J. J.

OPERATING ENGINEER

8-25-75

DATE

## PART 3 24-HOUR AEC NOTIFICATION (INCIDENTS)

☒ TPH

Feierabend

8/25/75

9:00 AM

REGION III

DATE

TIME

☒ TGM

Koppler

8/25/75

2:30 PM

REGION III &amp; DOL

DATE

TIME

IMMEDIATE OFF-SITE NOTIFICATION  
DIVISION MANAGER  
NUCLEAR STATIONSTITLE  
GENERAL SUPERINTENDENT  
SYSTEM ANALYSIS

TITLE

DATE

TIME

DATE

TIME

APPROVED DEVIATION REPORT

A. F. K. K.

STATION SUPERINTENDENT

8/25/75

DATE

## PART 4 RESOLUTION SUMMARY, INCLUDING EVALUATION OF CUMULATIVE EXPERIENCE OF PREVIOUS FAILURES OF SIMILAR SYSTEMS &amp; COMPONENTS.

ACCEPTANCE BY STATION REVIEW

DATE

RESOLUTION APPROVED AND  
AUTHORIZED FOR DISTRIBUTION

STATION SUPERINTENDENT

DATE