

LICENSEE EVENT REPORT

CONTROL BLOCK:

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE
NAME

LICENSE
NUMBER

LICENSE
TYPE

EVENT
TYPE

01 A L B R F 1

0 0 - 0 0 0 0 0 - 0 0

4 1 1 1 1

0 3

CATEGORY

REPORT
TYPE

REPORT
SOURCE

DOCKET NUMBER

EVENT DATE

REPORT DATE

01 CONT L L 0 5 0 - 0 2 5 9 1 1 0 3 7 6

EVENT DESCRIPTION

02 During the performance of a surveillance instruction, diesel generator D exhibited
03 an erratic speed behavior under load. Diesel generators A, B and C were operable.
04 The oil was changed in the Woodward governor hydraulic actuator and the diesel tested
05 satisfactorily and returned to service (BFRO-50-259/7623)
06

SYSTEM
CODE

CAUSE
CODE

COMPONENT CODE

PRIME
COMPONENT
SUPPLIER

COMPONENT
MANUFACTURER

VIOLATION

07 E B E M E C H U N N W 2 9 0 N

CAUSE DESCRIPTION

08 The erratic speed behavior of the diesel was apparently caused by dirty oil in a
09 Woodward governor model EG-B10 actuator.
10

FACILITY
STATUS

% POWER

OTHER STATUS

METHOD OF
DISCOVERY

DISCOVERY DESCRIPTION

11 B 0 3 0 NA B NA

FORM OF
ACTIVITY
RELEASED

CONTENT
OF RELEASE

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

12 2 2 NA NA

PERSONNEL EXPOSURES

NUMBER

TYPE

DESCRIPTION

13 0 0 0 2 NA

PERSONNEL INJURIES

NUMBER

DESCRIPTION

14 0 0 0 NA

OFFSITE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

TYPE DESCRIPTION

16 2 NA

PUBLICITY

8306240221 761124
PDR ADOCK 05000259
S PDR

17 NA

ADDITIONAL FACTORS

18 The oil in the governor will be replaced periodically

19

NAME: _____

PHONE: _____

GPO 891-667



TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

November 24, 1976



Mr. Norman C. Moseley, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., 8th Floor
Atlanta, Georgia 30303

Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 -
DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE
OCCURRENCE REPORT BFRG-50-259/7623

The enclosed report is to provide details concerning diesel generator D that exhibited an erratic speed behavior under load during the performance of a surveillance instruction. This report is submitted in accordance with Browns Ferry Technical Specifications Section 6. This event occurred on Browns Ferry Nuclear Plant unit 1.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure (3)
CC (Enclosure):
Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

12025

COPY SENT REGION *II*