

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME

LICENSE NUMBER

LICENSE TYPE

EVENT TYPE

7 8 9 14 15 25 26 30 31 32
 [A][L][B][R][F][1] [0][0]-[0][0][0][0][0]-[0][0] [4][1][1][1][1] [0][3]
 7 8 9 57 58 59 60 61 68 69 74 75 80
 [01] CONT [] CATEGORY [L] REPORT TYPE [L] REPORT SOURCE [] DOCKET NUMBER [0][5][0]-[0][2][5][9] [1][0][0][6][7][6] [] REPORT DATE []

EVENT DESCRIPTION

02 During startup testing at 1300 MWt, PS-74-8A (RHR pump discharge pressure switch) was
 03 found inoperative. Three of four redundant switches were operable.
 04 (BFRO-50-259/7621)
 05
 06

SYSTEM CODE

CAUSE CODE

COMPONENT CODE

PRIME COMPONENT SUPPLIER

COMPONENT MANUFACTURER

VIOLATION

07 [C][F] [E] [I][N][S][T][R][U] [N] [S][3][8][2] [N]
 7 8 9 10 11 12 17 43 44 47 48

CAUSE DESCRIPTION

08 Pressure switch PS-74-8A failed to operate when tested due to binding plunger.
 09 Static-O-Ring Model 5N-AA3-0/450 psi
 10

FACILITY STATUS

% POWER

OTHER STATUS

METHOD OF DISCOVERY

DISCOVERY DESCRIPTION

11 [B] [0][3][9] [NA] [B]
 7 8 9 10 12 13 44 45 46

FORM OF ACTIVITY RELEASED

CONTENT OF RELEASE

AMOUNT OF ACTIVITY

LOCATION OF RELEASE

12 [Z] [Z] [NA] [NA]
 7 8 9 10 11 44 45

PERSONNEL EXPOSURES

NUMBER

TYPE

DESCRIPTION

13 [0][0][0] [Z] [NA]
 7 8 9 11 12 13

PERSONNEL INJURIES

NUMBER

DESCRIPTION

14 [0][0][0] [NA]
 7 8 9 11 12

OFFSITE CONSEQUENCES

15 [NA]
 7 8 9

LOSS OR DAMAGE TO FACILITY

TYPE DESCRIPTION

16 [Z] [NA]
 7 8 9 10

PUBLICITY

8306240228 761007
 PDR ADOCK 05000259
 S PDR

17 [NA]
 7 8 9

ADDITIONAL FACTORS

18 This is not a repetitive occurrence and the entire switch was replaced and
 7 8 9

19 tested satisfactorily.
 7 8 9

PHONE:



TENNESSEE VALLEY AUTHORITY

CHATTANOOGA, TENNESSEE 37401

IE FILE COPY

October 27, 1976



Mr. Norman C. Moseley, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., 8th Floor
Atlanta, Georgia 30303

Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 -
DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE
OCCURRENCE REPORT BFRO-50-259/7621

The enclosed report is to provide details concerning the PS-74-8A
(RHR pump discharge pressure switch) that was found inoperative during
startup testing at 1300 MWt. This report is submitted in accordance
with Browns Ferry Technical Specifications Section 6. This event
occurred on Browns Ferry Nuclear Plant unit 1.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

Enclosure (3)
CC (Enclosure):

Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

11086