

LICENSEE EVENT REPORT

CONTROL BLOCK: 1 6

(PLEASE PRINT ALL REQUIRED INFORMATION)

LICENSEE NAME 01 A L B R F 3														LICENSE NUMBER 0 0 - 0 0 0 0 0 - 0 0										LICENSE TYPE 4 1 1 1 1					EVENT TYPE 0 3					
CATEGORY 01 CONT														REPORT TYPE L		REPORT SOURCE L		DOCKET NUMBER 0 5 0 - 0 2 9 6										EVENT DATE 1 1 2 6 7 6					REPORT DATE	

EVENT DESCRIPTION

02 During the performance of a scheduled maintenance test, start circuit 1 of D/G 3D was
 03 found inoperable because of a relay failure in the speed sensing circuit. The
 04 redundant start circuit 2 was operable. The relay was replaced. (BFRO-50-296/7619)
 05
 06

SYSTEM CODE 07 E B		CAUSE CODE E		COMPONENT CODE R E L A Y X				PRIME COMPONENT SUPPLIER N		COMPONENT MANUFACTURER E 1 6 0				VIOLATION N	
-----------------------	--	-----------------	--	-------------------------------	--	--	--	-------------------------------	--	-----------------------------------	--	--	--	----------------	--

CAUSE DESCRIPTION

08 An Electromotive Division model 8327263 relay failed in start circuit 1 speed
 09 sensing circuit, preventing the circuit from sensing diesel speed. The relay
 10 was replaced and the test in progress was completed.

FACILITY STATUS 11 B		% POWER 0 4 5		OTHER STATUS NA		METHOD OF DISCOVERY B		DISCOVERY DESCRIPTION NA	
FORM OF ACTIVITY RELEASED 12 2		CONTENT OF RELEASE 2		AMOUNT OF ACTIVITY NA		LOCATION OF RELEASE NA			

PERSONNEL EXPOSURES

NUMBER 13 0 0 0		TYPE 2		DESCRIPTION NA	
--------------------	--	-----------	--	-------------------	--

PERSONNEL INJURIES

NUMBER 14 0 0 0		DESCRIPTION NA	
--------------------	--	-------------------	--

OFFSITE CONSEQUENCES

15		NA	
----	--	----	--

LOSS OR DAMAGE TO FACILITY

16		NA	
----	--	----	--

PUBLICITY

17		S	
----	--	---	--

8306270023 761214
PDR ADDCK 05000296
PDR

ADDITIONAL FACTORS

18 This was a random failure and no additional action is required.

19

NAME: _____ PHONE: _____



TENNESSEE VALLEY AUTHORITY
CHATTANOOGA, TENNESSEE 37401

IE FILE COPY

December 14, 1976

Mr. Norman C. Moseley, Director
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region II
230 Peachtree Street, NW., 8th Floor
Atlanta, Georgia 30303

DEC 13 1976
U.S. NUCLEAR REGULATORY COMMISSION
REGION II

Dear Mr. Moseley:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 3 -
DOCKET NO. 50-296 - FACILITY OPERATING LICENSE DPR-68 - REPORTABLE
OCCURRENCE REPORT BFR-50-296/7619

The enclosed report is to provide details concerning start circuit 1 of D/G 3D that was found inoperable because of a relay failure in the speed sensing circuit during the performance of a scheduled maintenance test. This report is submitted in accordance with Browns Ferry Technical Specifications Section 6. This event occurred on Browns Ferry Nuclear Plant unit 3.

Very truly yours,

TENNESSEE VALLEY AUTHORITY

H. S. Fox
Director of Power Production

~~COPY SENT~~ REGION II

Enclosure (3)
CC (Enclosure):
Director (3)
Office of Management Information and Program Control
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director (40)
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

12761